


OneCNC Mill



OneCNC Mill is a hybrid CAD-CAM system with a user-friendly interface. OneCNC Mill simplifies the process of defining toolpaths for the machining of parts using CNC milling machines with up to 5 axes.

OneCNC integrates the Microsoft Windows interface with a powerful CAD engine. Parts can be designed and modeled in OneCNC, or imported from 2D or 3D CAD files. The part model and geometry data is directly available to the inbuilt CAM functions.

The purpose of this Manual

This manual covers OneCNC Mill Expert, Professional, Advantage, and Express. The manual provides information on how to get started and use OneCNC, it is not designed as a machining instruction manual.

Much of the information in this manual is also contained in the OneCNC Help file, which also contains tutorials and reference information about available procedures and commands.

CONTENTS

OneCNC Mill.....	1
OneCNC Environment	6
OneCNC Installation	7
Minimum System Requirements	7
OneCNC Installation	7
OneCNC Updates.....	10
Series 2 Dongle Installation - dongle numbers from 10000	11
Dongle Security	11
Series 1 Dongles - dongle numbers 1 to 9999	12
Start OneCNC and enter the Serial Key	13
Entering serials for optional modules.....	14
User profile selection	15
OneCNC Network Installation.....	17
Running OneCNC Dongle Server as a service.....	22
OneCNC User Interface	23
Toolbox	26
Right Sidebar.....	27
NC Manager.....	27
Layer Manager	28
Verify	28
History.....	28
Recent Files list.....	28
Status Bar.....	29
Preset Views.....	29
Construction Plane	30
Display mode.....	30
Section Tool.....	31
3D to 2D Automated drawing system	31
Drawing Color and Style selection.....	31
Modifying Entities.....	31
Quick Access Toolbar	32
Keyboard Shortcuts	33
Mouse Actions.....	34

OneCNC Overview	35
2D and 3D Geometry	36
3D Modeling	37
Toolpathing	38
Toolpath management	38
Toolpath Backplot.....	38
Metal Removal Simulation (OneCNC Mill and OneCNC Lathe only) ..	39
Outputting NC Files	40
OneCNC Integrated Help	41
Help	41
Tutorials.....	41
OneCNC CAD Tutorial 1.....	42
<i>Introduction To Cad Drawing</i>	<i>42</i>
Start a new drawing	42
Lines	43
Rectangle	48
Circles	50
Offset entities and boundaries.....	52
Moving Entities	56
Copy Entities	58
Rotate	60
Setting Current Drawing Properties.....	62
Trimming Entities	66
Chain Selection	71
OneCNC CAD Tutorial 2.....	75
<i>2D Drawing.....</i>	<i>75</i>
Step 1: Draw outer profile	76
Step 2: Draw the angled slot	83
OneCNC CAD Tutorial 3.....	90
<i>Solid Modeling by Extrusion</i>	<i>90</i>
Step 1: Complete CAD Tutorial 2 and save a copy.	90
Step 2: Create a solid by extrusion from curves.....	91
Step 3: Create the slot with an extrude cut.....	93
OneCNC CAD Tutorial 4.....	95
<i>Working With Planes.....</i>	<i>95</i>
Step 1: Draw a pyramid wireframe	96
Step 2: Position the plane.....	98
Step 4: Create the truncated pyramid	101
Step 5: Return to default XY plane.....	103

OneCNC Technical Drawing	104
<i>Automated 3D to 2D Drawing Layouts</i>	104
Add a drawing page with border and title block	105
Add views of the model to a drawing page layout.....	107
OneCNC Mill Tutorial 1.....	110
<i>Creating a Facing toolpath</i>	110
Step 1: Open the sample file and save a copy.	110
Step 2: Prepare for machining.....	115
Step 3: Facing toolpath	118
OneCNC Mill Tutorial 2.....	129
<i>Stock Toolpaths</i>	129
Stock toolpaths - Pocket, Profile and Chamfer	129
Step 1: HS Pocketing toolpath.....	129
Step 2: Mill Profile toolpath.....	136
Step 3: Chamfer toolpath	144
OneCNC Mill Tutorial 3.....	149
<i>Hole Feature Recognition</i>	149
Step 1: Hole Feature selection	149
Step 2: Drill Operation	152
Step 3: Counter Bore Operation	158
Step 4: Chamfer Operation	163
Step 5: Saving Hole Operation Settings.....	169
OneCNC Mill Tutorial 4.....	171
<i>The NC Manager and Outputting NC files.....</i>	171
NC Manager Groups and Operations	171
Duplicate an operation	172
To move an operation	173
The NC Processing dialog	174
NC Code output	175
Post Settings: Start And Finish Format	177
OneCNC Mill Tutorial 5.....	181
<i>Stock toolpaths - Cut Chain and Engrave All</i>	181
Cut Chain 2D	181
Cut Chain 3D	185
Engrave All 2D	191
Engrave All 3D	195
Advanced Stock Toolpaths	199

OneCNC Mill Tutorial 6.....	200
<i>Toolpath Templates</i>	200
OneCNC Mill Tutorial 7.....	206
<i>Model Toolpaths - Z Level Rough, Planar Finish</i>	206
Z Level Rough toolpath	208
Planar Finish toolpath	216
OneCNC Mill Tutorial 8.....	221
<i>Model Toolpaths - Semi Finishing.....</i>	221
Planar Semi Finishing.....	222
OneCNC Mill Tutorial 9.....	228
<i>Multiple Parts.....</i>	228
Defining repeats.....	230
Standard repeats	232
Subroutine repeats using multiple offsets	235
Subroutine repeats using a single offset	237
OneCNC Mill Tutorial 10.....	239
<i>Advanced Solid Model Toolpaths</i>	239
Plunge Roughing	240
Radial Roughing	241
Radial Finishing.....	241
Spiral Roughing.....	242
Spiral Finishing	242
Custom Roughing	243
Custom Finishing.....	243
Area Machining	244
Z Complete Finishing	245
Undercut Finishing.....	246
Constant Offset.....	247
Offset Finishing	248
Pencil Trace Finishing	249
Planar Steep Wall Finishing	250
Planar Shallow Finishing	251
OneCNC Support.....	252
OneCNC Global Offices.....	253
Copyright Notice.....	257

OneCNC Environment

OneCNC has been designed as an integrated manufacturing environment, with purpose built interaction between the CAD and CAM functions.

New users familiar with Windows-based software will be at home with the well organized pull-down menus, toolbox and shortcut keys together with meaningful graphics included throughout the software interface.

The interface is similar to other common Windows-based drawing software and provides compact access to frequently used functions. Users experienced with other mechanical CAD software will appreciate the ability to customize the functionality in a way they are used to using.

CAD functions

The CAD functions are used to draw and create parts.

Line, arc, and spline geometry can be combined with NURBS surfaces and solids in a hybrid modeling process. As well as the complete CAD functions for constructing parts from scratch, robust translators are provided for importing parts in other formats. 2D drawing and 3D modeling methods have been designed for ease of use.

CAM functions

The CAM functions are used to create the required NC program toolpaths for CNC machining of your parts. Toolpaths can be edited and reviewed in the NC Manager, which also has functions for backplot, real time preview, and metal removal simulation.

Multiple Views

OneCNC can show single or multiple views of the same object or model. Any view can be dynamically panned, rotated or zoomed. Multiple views make it easier for you to create complex models. While in a command it is possible to select a point in one view and then select the next point from another view.

Multiple Document

You can have more than one part drawing open in OneCNC. This makes it easy to cut and paste from one drawing to another and toggle between drawings. The Recent File tab shows previews of files to help you quickly find the drawing you want. Document management is simple in OneCNC due to the fact that the CAM data is stored in the drawing file.

OneCNC Installation

Minimum System Requirements

Operating System

Microsoft Windows 10, 8, 7, Vista or Windows XP (32 or 64bit)
Internet Explorer 7 or later
NTFS File System is recommended

Hardware

Minimum 1 GB of quality memory for Windows XP, or 3 GB of quality memory for Windows 8, 7, or Vista, especially if working with complex parts.

Pentium 4 single, dual, or quad core PC. AMD Athlon can be used only if later than 2004 with specs equal to the Pentium 4.

NVIDIA GeForce or similar OpenGL and DirectX graphics card, minimum 1Gb. It is essential you download and install the latest graphics driver for your card, as drivers supplied on install discs may be outdated due to production lead times.

A mouse with 3 or more buttons and a scroll wheel.

One available USB 1.1 or 2.0 port or a suitable parallel port depending on which licensing dongle you have.

CD-ROM drive for installation of standalone version if required.

Broadband Internet access is recommended for updating the software.

OneCNC Installation

You will need:

OneCNC installer disk or a downloaded update setup file

OneCNC dongle

CD Key and serial number

There are three steps to installing OneCNC on a single computer:


Install the software from disk or an update setup file

Plug in the dongle

Run OneCNC and enter the serial number to activate it

For network installations, network server software must be installed as well. That process is outlined in the next chapter.

All OneCNC products can be installed from the one installer package.



Insert the OneCNC CD or plug in the OneCNC flash drive.
Display the drive contents in Windows Explorer and double click
'onecnc_setup.exe'

Language Selection

Select your language from the drop down list.

Units Selection

Select the units you work in, Metric or Imperial (inches). This will set the default drawing units and post-processor configuration units. The units setting can be changed after installation using the Properties dialog on the File menu.


One CNC will open a file drawn in the alternate units at the correct real world size, but the NC toolpaths will be invalid, so you should save the files to separate locations.

CD Key


OneCNC installation requires a CD Key, which is usually found on the inside rear cover of this manual with your serial number, but is sometimes shipped separately from the software for security. Enter the CD Key and click the large 'play' button to start the installation.



The serial number will be requested when you first run the software. Keep a copy of your CD Key and Serial in a safe place as you will need them if you upgrade your computer and need to re-install.



The next dialog advises you to have all other programs closed, which is standard software installation procedure.



You then have the choice of where to install OneCNC. You can accept the default location or click the Browse button if you want to select your own location. Click Next when you are ready to continue.


In the confirmation dialog you can click Back to review your settings, or click Next to install OneCNC.



If you are upgrading from a previous version of OneCNC, the new installation will be in a new location.

You can still use your existing tool and material libraries, and custom Posts. To do this, copy the Settings folder from your previous installation to your new installation Settings location.

It is good practice to keep a backup copy of your Settings folder.



When all the files have been installed, click Finished to complete the installation. There will be a pause while the dongle driver for Series 1 dongles is installed.

When the installer closes, you are ready to insert the dongle and start OneCNC.

OneCNC Updates



Registered users can download updates of the setup file for their version of OneCNC at no extra charge.

Go to <http://onecncsupport.com/> and click on OneCNC Updates when you have read the update details. Click on Check For Updates.

Enter your dongle and serial numbers to enter the site. Click on the Register button on the next page to appear. Fill in your registration details, and click Save. Click on the Download button to go to the actual download page.

Select the check box to confirm you have read the update details, and click on the Download button. A dialog will appear asking if you want to Run or Save the file. Select Save and choose the folder on your computer to save the file in. Double click the downloaded file to install the update.

The update can also be accessed by clicking on OneCNC Updates in the Help menu, or the OneCNC Software Updates, Drivers and Posts link in the OneCNC Users Forum.

Dongle Installation

OneCNC requires a dongle for the licensed program to run. A dongle is a small hardware device which verifies your software license.

Series 2 Dongle Installation - dongle numbers from 10000

All OneCNC dongles with a number higher than 10000 are Series 2 dongles.



Series 2 dongles are USB HID devices which look like this. These dongles do not require drivers for a single computer installation.

If you have a network license you will need to install a network dongle driver, as described in the next chapter.

To install a Series 2 dongle

Make sure OneCNC is not loaded or attempting to load. To install the dongle simply plug it into a USB port on your computer. Basically, if the dongle fits, it's the correct port. Do not try to force the hardware or you may damage your computer or dongle.

If you have a timed licence the Windows date and time must be correct before connecting the dongle. It is recommended that the USB port a dongle is plugged into should not be used for other devices.

Dongle Security



Because it is the dongle which verifies your purchase of OneCNC, if a dongle is accidentally damaged or broken the damaged dongle must be returned to OneCNC before a replacement dongle can be issued.

If a dongle is lost or stolen, the replacement price is the full price for the software. Take steps to secure your dongle, and insure it for the replacement cost of the software.

Series 1 Dongles - dongle numbers 1 to 9999

If you have upgraded from an earlier version of OneCNC, you may have a Series 1 dongle with a number less than 10000.



These dongles may be USB or Parallel port dongles, and are now obsolete.

There is no 64 bit driver available for these older dongles, so if you have a series 1 dongle please see your OneCNC dealer for a replacement series 2 dongle.

A series 1 dongle will be replaced at no extra cost with any upgrade to the current version of OneCNC.

Note:


A series 1 dongle will not run the 64bit version of OneCNC.

Until you get your replacement dongle you can install the 32bit version of OneCNC on 64bit Windows by changing the last two digits of the CD Key to 32. For example the CD Key 6432 will install 32bit Mill Express which can be run with a series 1 dongle.

When you change to a new series dongle re-install OneCNC with the standard CD Key.

Start OneCNC and enter the Serial Key

Once installation is complete and the dongle is installed, OneCNC can be started. Double click on the OneCNC shortcut on your desktop, or select the OneCNC shortcut in the OneCNC folder in the Start menu.



The first time OneCNC is started the Licence Manager will look for the dongle. Select 'Single user licence' if you have a standalone installation, and click Continue.

Network licence - Series 2 dongle



To run OneCNC on a client PC connected to a network using a Series 2 dongle, you must select 'Network licence'.

To run OneCNC on a computer which is also the network server, the server installation needs to be set to 'Single user licence', as in this case the dongle is on the local system and not on the network.

The Licence Manager will open so you can enter the licensed user name and serial number.



The image shows a 'Licence Manager' dialog box with a title bar containing a close button (X). The main area is titled 'Enter your licence details :'. It contains the following fields and labels:


- Product : OneCNCXR8 64 Bit Mill 3D Expert - Version 62.4
- Client Number : CN12496
- Company Name :
- Email :
- Serial Number : - - -
- Licence Status : Enter your serial number

On the right side of the dialog is an image of a blue USB dongle. At the bottom right are two buttons: 'OK' with a checkmark icon and 'Cancel' with an 'X' icon.

The serial is made up of digits 0 to 9 and letters from A to F. The code must be entered exactly as it appears.

When the serial key has been entered the Licence Manager will indicate that the licence is acceptable, and the software can then be started.


Entering serials for optional modules




If you have a serial for an optional module, start OneCNC and click on Register Modules in the OneCNC Help menu.

Enter the serial in the dialog which opens, and the module will be activated.


User profile selection



OneCNC starts with this screen, which gives you the option of selecting the user profile you want to use. The user profile stores all your settings such as toolbar layout, interface color settings and your recent files list.




Clicking on the small arrow opens the user selection dialog, which allows you to select or create settings in the names of specific users for customizing.



Select the user profile you want to use from the list, and click OK.

You can create, delete, and rename user profiles using the buttons below the drop down list.



Click here to start OneCNC with the selected user profile.



If your user profile or other settings are not being saved, open Windows Explorer and right click on your Settings folder. Select Properties, and clear the "Read-only" check box. Click Apply and click OK to apply the change to all subfolders and files.

OneCNC Network Installation

This step is only necessary for network installations.

For network installations, network server software must be installed on the server or computer the dongle is plugged into.




Series 2 dongles use the OneCNC Dongle Server which is included in the OneCNC installer, and is accessed by a CD Key similar to installing the OneCNC software itself.

To install OneCNC Dongle Server on a computer or server with a Series 2 dongle, you will need:


- OneCNC installer disk or a downloaded update setup file
- OneCNC dongle
- Network CD Key and serial number




Run the installer on the server computer. To install the network dongle server software enter the CD Key 60200.




When the next dialog appears, enter the server software serial. The serial is made up of digits 0 to 9 and letters from A to F. This is not the same as the software serials which are entered later when installing the particular versions of OneCNC such as Mill and Lathe.




The next dialog advises you to have all other programs closed, which is standard software installation procedure.



You then have the choice of where to install the server software, the default installation is as shown.



The next dialog indicates you will need to unblock the firewall for this application only. Click Finish to complete the installation.




Here is the Windows Firewall dialog where you have to click Unblock for the dongle server software to work. This has no effect on network or internet security, it is only allowing any PC on the local network to access the OneCNC Dongle Server.

The server software is now installed and working.



There will now be an icon in the Taskbar at the bottom of your screen, indicating the dongle server software is running.

You can click the icon to open the Dongle Server interface, but it is not necessary to have the Dongle Server interface open for client computers to access the dongle.



The interface allows you to see how many clients are connected to the Dongle Server. You will not see a connection as shown here, until the OneCNC programs are installed on the client computers.

To install OneCNC on the client computers, start the OneCNC installer on each computer, and load the OneCNC application using the CD key for OneCNC.

Running OneCNC Dongle Server automatically


You can run OneCNC Dongle Server automatically so you do not have to start it if the server has been shut down.

Setting up a scheduled task will install OneCNC Dongle Server as a service which will automatically restart when the network server is started.

Firstly, install OneCNC Dongle Server as shown in the previous section. You can then use the Windows task scheduler to set up an action to start the OneCNC Dongle Server when the computer is started. You must be logged on as an administrator to perform these steps.

To open the Windows Task Scheduler, open Control Panel, click on System and Security, and click on Administrative Tools (if Control Panel opens in Classic view you can just double click on Administrative Tools). Double click on Task Scheduler.


In Windows Server, open the Server Manager and navigate to Server Manager > Configuration > Task Scheduler .




Click Create Basic Task. Enter the name and description for the task, and then click Next. Select When the computer starts, and click Next. Select Start a program, and click Next. Click Browse to find the OneCNC server program, which will typically be at C:\OneCNC Server\onecnc_server.exe Click Next when you have selected the program. Review the settings you have made and click Finish.

Restart the server to apply the changes you have made.

OneCNC User Interface



The OneCNC user interface has been carefully designed for ease of use.




Windows menus give you access to many features in OneCNC. Menu items with a pointer on the right side automatically open sub-menus which you can slide the mouse across to select from.




The Mill Expert interface is shown in this chapter. The available modeling and CAM functions you see will vary for different types or levels of OneCNC. OneCNC Solid Creator is intended for design only and has no CAM functions.

Drawing Window




The file you are working on is displayed in the drawing window, which is a real-time OpenGL model view. This allows you to view your object by means of dynamic rotation, panning and zooming.




Multiple Views of the same file can be shown. When parts become complex it can be useful to view and edit one object from various angles simultaneously. This function can be accessed from Window > Window Layout.


Multi Document



You can have more than one file open in OneCNC. When the file windows are maximized you will only see one file at a time. You can select the file to display from the Window menu.




Clicking the Restore Window button will display each file in its own window.



The file windows can be controlled by dragging, or using the Cascade and Tile commands on the Window menu.

Toolbox


The Toolbox is a menu system which is shown in the left sidebar.



When you start OneCNC you will see the toolbox Home menu.

The Home menu icons are grouped into commands for drawing, modeling, and CAM functions.

The toolpath functions available will vary with the version and level of OneCNC you are using.



Each icon in the toolbox Home menu will open a sub-menu from which you can select a specific command.

For many commands entry boxes will appear where you can input required values.

Click on the Home icon at the top of the Toolbox to return to the Home menu.


Clicking on the dotted button at the left of the toolbox will hide it.

Click on the button again to bring the toolbox back into view.

Right Sidebar

On the right of the screen the right sidebar has panels for:

- NC manager
- Layers Manager
- CAD Verify
- History
- Recent file list




Clicking on the dotted button at the right of the sidebar will hide it.

Click on the button again to bring the sidebar back into view.

NC Manager

The NC Manager displays the toolpaths you have defined.


Machining operations can be grouped, and operations can be renamed, edited, rearranged or duplicated.



Layer Manager

When you draw an entity it's created on the currently selected layer. The Layer Manager is used to create, name or delete drawing layers.


The panel shows a list of layers in a drawing. You can turn off a layer by closing the eye for that layer in the Layer Manager. Entities on the layer are still in the drawing but will not be visible.



Verify

The Verify panel holds tools to read data from geometry.


You can find exact values for position length or area for 2D entities, and volume of 3D solids. You can also find the angle and distance between entities.



History

As you construct your part, a record of commands used is created in the History tab.

You can roll construction back or forward like a multiple undo and redo. If you roll-back your history and start new construction, the rolled back construction is replaced with the new construction.




Recent Files list


When you save a file, a thumbnail image of it is added to the Recent file list.

The list shows if a file is open, active or closed.

You can open a closed file by clicking on the thumbnail image.



Status Bar




The Status Bar at the bottom of the OneCNC window provides you with functions related to the appearance of objects, and a message panel which shows prompts to help you use the program.

Preset Views

OneCNC has a set of preset views so you can select the direction you want to look at your model from.



Click on the View icon to open the preset view selector.



Click on the icon for the view you would like to change to.

For 3D modeling the Isometric or Trimetric Views are the most commonly used.

The CAD View is a special view optimized for 2D drawing, so it is not suitable for 3D commands. Use the Top View if you want to use 3D commands in a view similar to the CAD view.

Construction Plane

When you draw or model in OneCNC you can use a coordinate system which is independent of the world XYZ coordinate system.

OneCNC displays the Construction Plane which is a visual reference for the XY plane of the current construction coordinate system.



The Construction Plane is controlled using the Plane dialog, which is opened by the Plane icon in the Status Bar.


The Working With Planes tutorial in this manual covers the use of Construction Planes.

Display mode

Display controls the appearance of 3D surfaces and solids.



Click on the Display icon to open the Display mode selector.



Click on the icon for the display mode you would like to change to.

If you are extracting 2D profiles from 3D objects it can be useful to use the Transparent or Wireframe modes to access obscured parts of the model.

If you set the display mode to Wireframe, be sure to return it to another mode before attempting any modeling commands as you will not see any surfaces or solids.

Section Tool



The Section tool is used to view a cross-section of your work parallel to the current working plane. It can also be used to create section geometry.

3D to 2D Automated drawing system



In Expert versions of OneCNC and OneCNC Solid Creator you will see the Pages icon which opens the automated 3D model to 2D CAD drawing system. This can be added as an optional module to OneCNC Professional versions.

Drawing Color and Style selection



OneCNC has a 2 color drawing system. Color selection boxes in the Status Bar set the color for new entities. The color selection box on the left is for geometry and that on the right is for surfaces and models.




To select the line style and line thickness for new geometry entities click the Styles icon.

Modifying Entities



Click Modify to change the color, line thickness, line style or layer of existing entities.




Select the check boxes for the attributes you want to change and select the new values.


Quick Access Toolbar



The Quick Access toolbar is a custom toolbar you can use to display icons for commands you use often.



When you install OneCNC the Quick Access toolbar will be empty except for the Quick Access icon. Click on the Quick Access icon to open the Quick Access customization dialog.



Select the command you want to add in the Commands list on the left of the dialog. A keyboard shortcut can be assigned to the command in the 'Assign hot key' entry box.

You can right click on an icon you use regularly to add it to the Quick Access toolbar.



Keyboard Shortcuts

OneCNC provides a default set of keyboard shortcuts, which are a powerful way of accessing functions quickly by pressing a key or combination of keys. You can add your own keyboard shortcuts in the 'Assign hot key' entry box of the Quick Access dialog.

The following lists give the default shortcut key settings in OneCNC.

View shortcuts

Arrow Keys	Rotate model horizontally and vertically
Arrow Keys + Shift	90 Deg steps rotate right left up down
Ctrl + Arrow Keys	Pan
Space Bar	Preset View selection dialog
Space Bar double press	CAD View
Delete	Delete selected entities
F	Zoom to fit
Z + Shift	Zoom in
Z	Zoom out
W	Zoom to a window
Ctrl + 1	Top View
Ctrl + 2	Bottom View
Ctrl + 3	Left View
Ctrl + 4	Right View
Ctrl + 5	Front View
Ctrl + 6	Back View
Ctrl + 7	Isometric View
Ctrl + 8	Trimetric View
Ctrl + 9	Dimetric View
Ctrl + 0	Default View

Drawing shortcuts

P	Point
L	Line
R	Rectangle
O	Offset
H	Hatch
C	Circle with given radius
Ctrl + F	Fillet Arc

File shortcuts

Ctrl + N	New file
Ctrl + O	Open file
Ctrl + S	Save file
Ctrl + Tab	View next open file
Ctrl + P	Print

Edit and modify shortcuts

S	Select Single
L	Select nearest line when in Single Select
mode	
A	Select nearest arc when in Single Select
mode	
Ctrl + A	Select All
Ctrl + Z	Undo
Ctrl + Y	Redo
Ctrl + X	Cut to clipboard
Ctrl + C	Copy to clipboard
Ctrl + V	Paste from clipboard
Ctrl + D	Delete
M	Move
B	Blank selection
T	Trim One
Ctrl + T	Trim Two



Mouse Actions

Left Button	Enter / Select
Right Button	Escape / End Function
Mouse Wheel	Zoom to/from cursor
Middle Button + Ctrl	Pan
Middle Button	Rotate view
Middle Button + Shift	Zoom

OneCNC Overview

The purpose of OneCNC is to create NC code programs for CNC machines. The workflows for the various types of OneCNC are as follows:

OneCNC Mill or Mill with Multi-axis module

1. Draw or import part geometry or model
2. Define toolpaths to cut the part
3. Preview or simulate to verify toolpaths
4. Output NC program to send to the machine

OneCNC Lathe

1. Draw or import part geometry or model
2. Define toolpaths to turn the part
3. Preview or simulate to verify toolpaths
4. Output NC program to send to the machine

OneCNC Lathe with Mill-Turn module

1. Draw or import part geometry or model
2. Define turning and live tooling toolpaths
3. Preview or simulate to verify toolpaths
4. Output NC program to send to the machine


OneCNC WireEDM

1. Draw or import part geometry or model
2. Define wirepaths to cut the part
3. Preview to verify wirepaths
4. Output NC program to send to the machine

OneCNC Profiler (Nesting for plasma, laser, waterjet or router)

1. Draw or import part geometry
2. Add part shapes to the Parts list
3. Nest parts to sheets
4. Define drill, engrave and cutting operations for the nested sheets
5. Preview to verify toolpaths
6. Output NC programs to send to the machine

2D and 3D Geometry



Geometry drawing

OneCNC parts are constructed using pure geometry. Boundaries can consist of lines, arcs or splines constructed in 3D space.

Layers

The Layer Manager sidebar panel is used to create, select, open and close layers which are used to organize your drawing.

Dimensions and Text

All 2D and 3D geometry can be dimensioned and annotated. Text labels can be added to parts and converted to geometry for engraving.

Drawing Layout Patterns


Borders, title and revision blocks, and bill of material lists can be saved as patterns and loaded into drawings as required.

3D to 2D Technical Drawing System

Expert versions of OneCNC include the 3D to 2D drawing system which automates the preparation of 2D drawings for printing. 2D technical drawings are created as page layouts in your ONECNC file, using title block and border templates. 2D views of the 3D part model can be created automatically and added to a technical drawing. The system can be added to Professional versions of OneCNC as an optional module.

3D Modeling

Available in OneCNC Expert and Professional versions



Surfaces Creation

Planar and curved surfaces can be constructed using the many available strategies.

Solids Creation

Solids creation from Primitives allows you to create basic shapes such as Cubes, Spheres, and Cylinders. Solids can also be created by revolving or extruding geometry.

Hybrid Solids Creation

In the hybrid modeling technique a closed set of surfaces can be unioned to become a new solid. Existing solids can be merged with a closed set of surfaces to become a new solid.

Model Operations

New solids can be created by the cutting, uniting or intersection of existing solids. Solids can be split by a plane, or broken into separate surfaces.

Expert Tools

Expert versions of OneCNC have additional advanced modeling tools.

Toolpathing

In all versions of OneCNC except Solid Creator, toolpaths can be defined by clicking an icon in a Toolpaths menu in the Toolbox and completing any selection or settings entries that the toolpath requires.

Toolpath management

When you define a toolpath it will be added to the active toolpath group in the NC Manager.

An NC file can be output from a single operation, all the operations in a single group, or all operations in all groups in the NC Manager.

Right clicking on a group or toolpath will open a context menu with commands for frequently used functions such as preview and backplotting.

In Mill or Lathe the lower section of the NC Manager displays settings for the currently selected toolpath which can be edited.

NC Manager

mill express pocket


Express_1 Default post

- 1: Mill Pocket on
- 2: Mill Profile on
- 3: Rectangular groove on
- 4: Circular Groove on
- 5: Large Hole on
- 6: Simple Hole, 10mm bolt, Z0 to Z-25 on

20 MM CARBIDE END MILL


Tool diameter	20 mm
Tool tip radius	0 mm
Material top	Z0
Max cut depth	25.5 mm
Final Z clearance	5
Rapid clearance	5
Station number	2
Length offset	2
Diameter offset	2
Spindle Speed	4392
Coolant	No.1
Work offset	G54
Feedrate	773
Plunge feedrate	386

Toolpath Backplot




Toolpaths can be backplotted, which means they are drawn as geometry on a special layer named Backplot. Feed moves are drawn in green, and rapid moves in orange. Reposition moves in highspeed machining are drawn in blue.

Toolpath Preview



The Live Preview window shows an animated preview of the toolpath, backplotting as it goes. In Mill or Lathe the cutting tool will be shown traveling along the toolpath.

Metal Removal Simulation (OneCNC Mill and OneCNC Lathe only)



In all levels of Mill and Lathe, OneCNC provides real-time toolpath metal removal simulation. By simulating the feed and speed of the process, you can check the machining operation prior to sending to the CNC machine.

OneCNC Mill also provides Rest Material Verification, which highlights the thickness of material left on the part until it is fully machined.



NC Processing

Process Toolpath Group Multiple Parts

Simulate / Rest

Post

Job Sheet

Backplot

Preview

Quick Check

Post: Default Setup

Status: ☒ On ☐ Off

Description: Express_1

Program Number: 4532

Part Number: P000034

Author: OneCNC

Workshift: X0.000, Y0.000, Z0.000 Set

Table Load Move: None Set

Notes: Express Demonstration Part

Renum operations

OK Cancel

Clicking the Process icon in the NC Manager opens the NC Processing dialog. You can enter notes or a program number before the file is output. OneCNC formats the NC file using a machine specific definition called a 'Post'. OneCNC is supplied with Posts for all popular machines, and it is easy to create a custom Post by copying and editing an existing format.

```

mill express pocket.NC - OneCNC Link
File Edit View Tools Bookmarks Help
O4532
N10 (PART - P000034)
N20 (NOTES - EXPRESS DEMONSTRATION PART)
N30 G00 G17 G40 G49 G80 G90
N40 (10 MM 1.0R CARBIDE BULLNOSE)
N50 T1 M06
N60 G00 G90 G54 X140.155 Y70.039
N70 S8785 M03
N80 G43 H1 Z5.
N90 M08
N100 G00 X140.155 Y70.039 Z5.
N110 Z1.
N120 G01 X141.369 Y70.349 Z0.956 F316.0
N130 X142.467 Y70.951 Z0.912
Configuration: default
Line 1 Col 1

```


Editing and sending the created program

When you output the NC file for your job it will open in OneCNC Link, the complete editor and DNC transfer program, where you can see your NC code before the final stage of sending the completed NC program to the CNC machine.

OneCNC Integrated Help

At OneCNC we put a lot of effort into making OneCNC the world's easiest CAD/CAM package to use. OneCNC has several features within the program to help new users quickly adapt to its powerful but easy to use features.


Help



If there is a specific part of the program you want to learn about, click on Contents in the Help menu.

The help files will open in a new window, with navigation controls at the top. The Back or Forward buttons allow navigation between help files you have visited, like an internet browser. The Home button will return you to the first page shown on the screen.

Tutorials



Clicking on Tutorial in the Help menu will take you straight to the OneCNC Tutorials folder in the Help files.

There are step by step tutorials for 2D CAD, 3D modeling, and how to define machining toolpaths for each version of OneCNC.

Context Sensitive Help

OneCNC uses Context Sensitive help. This means if you are using a function and need help on it, press F1 and OneCNC Help will open showing the relevant topic.

OneCNC CAD Tutorial 1

Introduction To Cad Drawing

This Tutorial is designed for all OneCNC products.

This tutorial will quickly take you through the essential functions for drawing and modifying geometry in OneCNC, to get you up to speed in the shortest possible time. In the exercises in this chapter, exact positioning is not important. The aim is to get an overall view of the process of drawing in OneCNC.

Start a new drawing

When you start OneCNC you will have a new file ready to draw in.



You can also start a new file by clicking on the New File icon in the Standard toolbar.




The first thing you should do when starting work in a new file is to click Save and save the .ONECNC file. If you save this tutorial you will be able to open it and resume where you left off if you are interrupted.



It is good practice to save your file regularly as you work. When working on complex parts, you can use the Save As command on the File menu to make incremental copies of your work, saving as "file_01.ONECNC", "file_02.ONECNC", and so on.


It is strongly recommended that you save a backup of all your work in another location once a day, and in an offsite location every week.




The part will open in the default 3D view. The darker rectangle is the construction Plane, which indicates the XY plane of the coordinate system you will be drawing in. Later you will see how you can move and rotate the Plane to define a new coordinate system but for now we will leave it in the default XY position.

Lines

We will start with lines, the most common drawing entity.



Click on the Line icon to open the Line menu in the toolbox.




The Line icon in the Line menu is highlighted, showing that the Line command is started automatically.


When the Line command is active, coordinate entry boxes will be available in the toolbox. Coordinate entry can be used for the first or second point of any line segment.

You can enter coordinates for a position in the World coordinate system, or the coordinate system of the current plane.


The current mouse pointer position is displayed in the toolbox, so you can also use it to check the position for a grid snap.




The mouse pointer will snap to grid positions in the drawing plane. Click to select a start point for the new line.




The mouse pointer will have a preview of the line to be drawn attached to it. Click on a new grid point to draw a horizontal line.




The Line command draws consecutive lines. Click again to draw a vertical line from the last point.




Move the mouse pointer horizontally again and you will see an indicator line when the new line endpoint is aligned with the start position. Click to end the line on the vertical alignment.



Hold the mouse pointer near the start of the chain of lines and you will see the Endpoint indicator. Click to end the new line on the first line endpoint.




Hold the mouse pointer near the previous line and you will see the Midpoint indicator. Click to end the new line on the previous line midpoint.



Right click to end the chain of lines.

The Line command will still be active. You can start a line at a new position and continue as before.



Click near a line you have already drawn. The start point will be on the existing line.


coordinate	
World :	On plane :
X-Coord 10	10
Y-Coord 20	20
Z-Coord 0	0
<input checked="" type="checkbox"/> ok	+ Inc
parameters	
Line Length	0
Line Angle	0
adjust along position	
Distance along	15
Ratio along	0.3

The toolbox will display the distance the new start point is along the existing line.


Change the value in the Distance along entry box to move the start point to a new position along the base line.

If you prefer you can enter the position on the base line as a ratio of the base line length.

The Distance along and Ratio along values are interactive.



Move the mouse pointer near another line and click to connect to it.



Right click twice to end the Line command.



Click on the Select All icon to select the lines you have just drawn.



Click the delete icon to clear the drawing area.



Start the Line command again and practice drawing lines. You can enter an exact position for a line endpoint by entering coordinates in the toolbox. You can also define a line by entering a value for line length, or angle from the last line segment.

Delete the lines when you are ready to continue.

Rectangle

The Rectangle command creates a rectangle with the option of a given radius fillet on all the corners.



Click on the Rectangle icon in the Line menu to start the Rectangle command.

coordinate

World :	On plane :
X-Coord 0	0
Y-Coord 0	0
Z-Coord 0	0


☒ ok

parameters

Corner Radius 5


When the command is started, you have the option of entering a corner radius value.

Enter a Corner Radius of 5.




To define the first corner of the rectangle you can click on an entity or grid snap, or enter coordinates in the Toolbox.

This will be the point where the sides of the rectangle intersect before they are filleted.



A preview of the rectangle is shown, with the second corner attached to the mouse pointer. Click on or enter a position for the second corner. The second corner can also be set by entering an X length and Y width for the rectangle.



The mouse pointer is still active, ready to select a start corner for a new rectangle.

Draw some more rectangles, using different options such as a zero Corner Radius, or using values for Length or Width.



Right click when you are ready to end the command.




Click on the Select All icon to select the rectangles you have just drawn.



Click the Delete icon to clear the drawing area.

Circles

The Circle command creates a Circle with a given diameter.



Click on the Arc icon to open the Arc menu in the toolbox.



The Circle icon in the Arc menu is highlighted, showing that the Circle command is started automatically.

coordinate

World : On plane :

X-Coord

0

0

Y-Coord

0

0

Z-Coord

0

0

☒ ok


+ Inc

parameters

Diameter


35

Enter a Diameter for the circle in the Toolbox.




A preview of the circle is attached to the mouse pointer.


Click on or enter a position for the center of the circle.



The Circle command continues and you can place another circle by its center point.



You can change the Diameter in the Toolbox before placing the next circle.




Right click when you want to end the Circle command.



Click Select All and then click the Delete icon to clear the drawing area.


Offset entities and boundaries

An offset entity or boundary is often needed when drawing a part. In OneCNC this is done using the Parallel/Offset command.




To practice the Parallel/Offset command, draw a rectangle with filleted corners.


Offsetting single entities




Click on the Parallel/Offset icon in the Line menu to start the command.




When the command is started, enter the distance you want to offset in the Offset Amount entry field in the Toolbox.




Select a side of the rectangle.



Move the mouse pointer around, and you will see a preview of the selected entity being offset. When the preview is where you want the offset, click to create the offset entity.




You can now select another single entity, and create an offset by clicking when the preview is where you want the offset.



Right click to end the command when you have finished making single offsets.


Offsetting a boundary




Delete the single offsets you made, or click on Undo till you return to the rectangle with filleted corners.




Click on the Parallel/Offset icon in the Line menu to start the command.




Enter the distance you want to offset in the Offset Amount entry field in the Toolbox.




Select the same side of the rectangle.
The single offset preview will appear, but do not click to place it.



Move the mouse pointer near the end of the selected line, and the connected boundary will be highlighted. Click to select the boundary for offsetting.



Now the preview will show a preview of the entire boundary being offset. Click to place the offset. The command will recur.




Right click when you have finished creating offsets.



Select All and Delete before continuing.

Moving Entities


Entities can be moved, copied, scaled, rotated and mirrored. These Transform functions can be accessed by clicking on the Transform icon in the Toolbox to open the Transform menu.



We will start with the Move command. Use grid snaps to draw a square evenly spaced around the world origin, and draw two circles on the corners at the left of the square.




Before starting a Transform command, entities must be selected. Click on the Select icon to select entities one at a time.



Click on each of the circles to select them. Selected entities change color to red when they are selected. If you select an entity by mistake, click on it again and it will be removed from the selection set.




Right click to finish selecting.




Click on the Transform icon to open the Transform menu in the toolbox.



The Move icon in the Transform menu is highlighted, showing that the Move command is started automatically.




You can select or enter a position as the start point for a move. Click on the midpoint of the line between the circles.



A preview of the entities being moved will be attached to the mouse pointer. Shadows indicate the original position of the entities. Click on the midpoint of the opposite line to move the circles.




Right click to end the Move command. The moved entities are still selected, ready for another command.



Click Deselect All to leave the circles unselected.


Copy Entities




Click on the Select icon, and select the circle at the top of the square.




Right click to end the selection.



Click on the Copy Move icon in the Transform menu of the toolbox to start the Copy command.




Select the intersection of the circle and the right side of the square as the start point of the move.




Move the mouse pointer to the left side of the square. Click on the intersection of the left side of the square and the dashed horizontal indicator to set the finish point of the move.



Right click to end copying from the current start point.



The Copy move command is still active. Select the center of the circle as the start point for another copy.



Click on the diagonally opposite corner of the square to create a copy there.



Right click to end the current copy.




Right click again to end the Copy move command.



Click Deselect All to leave the original circle unselected.

Rotate

Entities can be rotated about a selected center of rotation. The axis of rotation can be parallel to the X, Y, or Z axis of the World or Plane coordinate system.




Select all the sides of the square.




Right click to end the selection.



Click on the Rotate icon in the Transform menu.




To select the center of rotation, move the mouse pointer to the intersection of the X axis and Y axis. Click when the square World origin indicator appears.



To create the rotated square as a copy of the original, enter 1 for the #Copies value in the Toolbox.

The toolbox now shows six options for the axis of rotation. The default rotation mode is Rotation Z plane, which rotates entities in the current drawing plane.

You can enter the exact degrees of rotation in any of these fields, but for common rotation amounts a rotation protractor with markers at 15° intervals is shown in the drawing window.



Move the mouse pointer around the protractor, and click to rotate the square by 45°.



Right click twice to end the rotation command.



Click Deselect All to leave the original square unselected.

Setting Current Drawing Properties

OneCNC has a 2 color drawing system, controlled by color selection boxes in the Status Bar.



The color selector on the left is for geometry and that on the right is for surfaces and models. To set the current color, click the selector and select the color you want to use. To switch back to the default color just click the small square in the corner of the selector.




To select the line style and line thickness you would like all new entities to be drawn with, click the Styles icon.

OneCNC uses red to indicate an object is selected, so don't use red for drawing.


Using Layers

Every entity created in OneCNC is said to be 'on' a Layer. Layers give you control over entities on each layer as a group. For example, if you draw dimensions on a layer named 'Dimensions', you can then turn off display of the layer to hide all dimensions while working on the drawing geometry.


Click on the Layer tab at the lower right of the screen to open the Layer Manager.




Up till now you have been working in a new file, on the default layer, Layer 1. We will now create a new layer and move some of the geometry to the new layer.




To add a new layer, click on the + icon at the top of the Layer Manager.




The new layer is created with the default name Layer 2. Click on the icon next to the + icon to rename the layer.



Enter 'Circles' as the name for the new layer, and click OK.



The Layer list is sorted alphabetically, so the Circles layer is now above Layer 1. It is highlighted in blue, indicating it is the active layer new entities will be created on, but the X in the visibility column shows it is an empty layer.




Select all the circles in your practice drawing.




Click on the Modify icon in the Status Bar.

Default Layers


You can set default layers to be contained in each new drawing from the File menu > Properties dialog. Select the Layers tab, click New, give the layer a name, and set a default color, line type, and width.




In the Modify Selected Attributes dialog, you can change the color, line type, thickness, or layer of entities. Select the Circles layer in the Layer list to move the selected entities to that layer.



There is now a green eye icon in the Circles layer visibility column, indicating all entities on the layer are visible. The red selection square indicates all entities on the layer are selected. Click on the square to deselect the circles.



Click on the open eye icon for the Circles layer and it will close. This will turn off display of all entities on the layer.




Now you will be able to see the squares clearly.

Trimming Entities

Trim functions are used to shorten or extend existing entities.

Scissors


The quickest way to trim away unwanted parts of geometry is to use the Scissors tool.




Click on the Trim/Break icon in the Toolbox to open the Trim/Break menu.




Click on the Scissors icon to start the Scissors command.



Click on an unwanted part of a line or arc.



The geometry will be trimmed back to the next intersection with another line or arc, and the command continues. You can continue trimming by clicking on unwanted parts of geometry.




Right click to end the command when you have finished trimming entities.




The Scissors command cuts entities back to the next intersection or endpoint in each direction from the point where you clicked on the entity. If you click on an entity which is not crossed by another line or arc, it will be deleted.

Trim Two


This function will shorten or extend two arcs or lines to their common intersection. It is an important function as it can be used to make sure a chain of entities are properly connected at their endpoints.




Open a new file to practice using the Trim Two command. Draw some lines that cross, and some unconnected lines.




Start the Trim Two command by clicking the Trim Two icon in the Trim menu of the Toolbox.



Click on the first line you want to trim, on the side of the intersection that you want to keep.




Click on the second line you want to trim, on the side of the intersection that you want to keep.




The lines will be trimmed to their intersection. In this example both lines were shortened.


The command continues, and you can click on the next line you want to



trim.



Click on the next line to trim. In this example one line will be shortened and one will be extended to meet at their intersection.



Right click to end the command when you have finished trimming. The four lines in this example have now been trimmed to form a closed boundary.



Click Select All and then click the Delete icon to clear the drawing area.




Some CAM operations require selection of consecutive entities as a profile chain.

Trim Two ensures that the junction between two entities is properly trimmed for chain selection, and can be used to repair a chain that will not select properly.

Chain Selection

Chain selection is an important function that selects consecutive entities to form a profile chain. A profile chain can be open or closed. For many CAM functions you will need to select a profile chain of consecutive entities as the first step of the toolpath definition.




To practice chain selection, draw a filleted rectangle.


Selecting a complete profile as a chain




Click on the Chain Selection icon to enter chain selection mode.




The mouse pointer changes to the word 'start'.
Click on the entity that will be the first in the chain.



Move the mouse pointer around till the red arrows are pointing in the direction that you want to chain select. Click to set the direction.



The mouse pointer changes to the word 'end'. Click on the last entity of the chain you want to select, or press the F3 key to select all consecutive entities automatically.



The chain will be selected. You can now start to select another chain, or right click to end chain selection.


Selecting part of a profile as a chain




Click on the Deselect All icon to clear the previous selection.




Click on the Chain Selection icon to enter chain selection mode.




The mouse pointer changes to the word 'start'.
Click on the entity that will be the first in the chain.




Move the mouse pointer around till the red arrows are pointing in the direction that you want to chain select. Click to set the direction.



The mouse pointer changes to the word 'end'. Click on an entity to end the chain.



The mouse pointer is still seeking a chain end. You can click further along the chain to add one or more entities to the chain selection.




Right click when you are ready to finish selecting the chain. You can now start to select another chain, or right click again to end chain selection.

OneCNC CAD Tutorial 2

2D Drawing

This Tutorial is designed for all OneCNC products.




In this tutorial we will be using some of the time saving features of OneCNC CAD drawing to show how easily a part can be constructed. We will be drawing a part with fillets and chamfers, and a slot at an angle of 75 degrees.

Start a new file, and save it as 'Cad Tutorial 2'.



Click on the View icon in the Status Bar to open the View menu, and select CAD View.


CAD view is a special top down view, specifically for 2D drawing in the



XY plane.

While in CAD view all drawing is in World coordinates.

Step 1: Draw outer profile




Click on the Rectangle icon in the Line menu to start the Rectangle command.

Enter 0 for Corner Radius, to draw the rectangle with sharp corners.



Enter coordinates in the toolbox or use a grid snap to start the rectangle at X10 Y10. You can then enter 150 for Length and 100 for Height to make the rectangle 150 wide in X and 100 high in Y.

To create the semi-circle on the right side of the part, start the Arc



Sketch command on the Arc menu.

Click on the midpoint of the vertical line at the right side of the part to



locate the center of the arc.

The Arc Sketch function now requires the arc Radius, Start Angle, and End Angle. Each of these can be defined by entering a value in the toolbox, or clicking on an entity or grid snap.

coordinate	
World :	On plane :
X-Coord 175	175
Y-Coord 60	60
Z-Coord 0	0
<input checked="" type="checkbox"/> ok	

parameters	
Radius	15
Start Angle	0
End Angle	0


Enter 15 in the toolbox for the Radius of the arc.




Click on the endpoint above the arc center to set the Start Angle to 90°.



Click on the endpoint below the arc center to set the End Angle to 270°.



Right click to end the Arc Sketch command.



To draw the angled line at the top left of the part, select the Line menu to start the Line command.



Click on the vertical line at the left of the part, between the midpoint and upper end.

parameters

Line Length
0

Line Angle
-90

adjust along position

Distance along
40

Ratio along
0.4

To fix the start point of the line at 40mm from the end of the selected line, enter 40 as the Distance along value in the toolbox.

parameters

Line Length

Line Angle


adjust along position

Distance along


Ratio along

Enter -60 for the Line Angle.

This will fix the angle of the new line at 60° from the direction of the anchor line.




Move the mouse pointer along the new line preview until it locks onto the horizontal line at the top of the part, and click to draw the line.




Right click to end the Line command.


We can now trim away the unwanted line segments.



Start the Scissors command on the Trim/Break menu.



Click on the segment within the semicircle to remove it.




Click on the segments at the top left of the part to remove them.




Right click to end the Scissors command.


Next we will create the fillet on the lower left corner of the part.




Start the Fillet command on the Arc menu.




Enter a Fillet Radius of 25 in the toolbox.



Click on the left side of the part near the lower left corner.




Click on the lower side of the part near the lower left corner.




The fillet is created, and the corner is trimmed automatically.

Right click to end the Fillet command.


Next we will create the chamfer on the lower right corner of the part.




Start the Chamfer command on the Line menu.




Enter a Chamfer Distance of 15 in the toolbox.



Click on the lower side of the part near the lower right corner.



Click on the right side of the part near the lower right corner.




The chamfer is created, and the corner is trimmed automatically.


Right click to end the Chamfer command.

Step 2: Draw the angled slot


The first step in construction of the slot will be to draw the centerline.




Select the Line menu to start the Line command.



Move the mouse pointer near the center of the fillet arc, and click to place the start point of the line there.




Type 25 in the Line Length box, and press Enter.




Type 45 in the Line Angle box and press Enter again.

The line will be drawn.

Right click to end the current Line sequence, and right click again to end the Line command.



The part drawing should now look like this.



Start the Circle command to draw circles which will become the arcs at each end of the slot.

coordinate

World :
On plane :

X-Coord 0 0

Y-Coord 0 0


Z-Coord 0 0

☒ ok
+ Inc

parameters

Diameter 10

Type 10 in the Diameter entry box.



Click on the lower endpoint of the centerline to draw the first end arc of the slot.

coordinate

World : On plane :

X-Coord 35 35

Y-Coord 35 35


Z-Coord 0 0

☒ ok + Inc


parameters

Diameter 20

Type 20 in the Diameter entry box.




Click on the upper endpoint of the centerline to draw the second end arc of the slot.





Right click to end the Arc command. You should now have two circles of unequal diameter, one at each end of the centerline.



Next we will join the circles with tangent lines.




Start the Line Tangent command in the Line menu of the Toolbox.



Draw the first tangent line by clicking near where the tangents will be.




Draw the second tangent line by clicking near where the tangents will be.



Right click to end the Line Tangent command and you will have two tangential lines as shown here.



Begin the Single Selection command.




Select the 45 degree centerline.



Right click to end the selection process.



Click the Delete icon or press the Delete key to delete the centerline.





All we have to do now is trim the circles to the tangent lines to finish the slot.





Scissors




Start the Scissors command on the Trim menu.



Click on the unwanted segment of the lower circle to trim it away. Circles have an endpoint at 0° so you must click twice to remove both ends of it.



Click on the unwanted segment of the upper circle to trim it away. The remaining arc will be composed of two arcs because of the circle endpoint at 0° . It is good practice to trim this to one arc. Click below the 0° endpoint to remove the smaller arc.




Because the smaller arc is not crossed by any other entity, the Scissors command removes it completely.




Right click to end the Scissors command.


Start the Trim Two command.



Click on the tangent line to select it as the first entity to trim. Click between the endpoint and the midpoint of the line.



Click on the arc to select it as the second entity to trim.




The two entities will now be joined perfectly.

Your drawing should now look like the picture at the beginning of this tutorial, which is now complete.

OneCNC CAD Tutorial 3


Solid Modeling by Extrusion

This tutorial is intended for Expert and Professional versions of OneCNC.




In this tutorial we will use OneCNC solid extrude commands to construct a 3D solid part. You will need the outlines drawn in CAD Tutorial 2 before attempting this tutorial. We will extrude the part with a taper angle and cut the through slot with vertical walls.

Step 1: Complete CAD Tutorial 2 and save a copy.




Complete 'CAD Tutorial 2' and save the file. Use Save As on the File menu to save a copy as 'CAD Tutorial 3'. Press the Space bar and set the view to Trimetric. Your part should appear as shown in this image.


Step 2: Create a solid by extrusion from curves.



Click on the Extrude icon in the Toolbox to open the Extrude menu.




Click on the Extrude Curves icon.




Enter a Taper Angle of 15 in the parameters section of the Toolbox. This will tilt the walls of the extrusion inwards.

Leave the Linear Corners check box unselected.



OneCNC now seeks a boundary to create an extrusion from. Hover the mouse anywhere near the external boundary and click to select it as the outline of the part. The entire outer boundary will be selected with one click.




You can extrude a shape with one or more openings, so the cursor will continue to seek boundaries.


Do not select the inner boundary.




Right click to end the selection stage of the command because in this case we want to create the slot using different settings.



The height of the extrusion can be set by a mouse click or by entering the height in the toolbox. As you move the mouse, you will see a preview of the extrusion, and the current height will be displayed in the toolbox height entry.



Enter a Height of 10 in the parameters section of the Toolbox, and press the Enter key.



Click in the drawing window and the extruded solid is created with an external taper of 15 degrees.




Right click to end the command.

Step 3: Create the slot with an extrude cut

The slot boundary we want to use is obscured by the solid we have made. We could change the view direction but there is no need to do this, as we can change the model display setting to Transparent.




Click on the Display icon to open the Display menu.




Select Transparent. The slot geometry will now be visible through the part.


Click on the Extrude cut icon in the Extrude menu.




Change the Taper Angle to 0 so the slot will have vertical walls.



Select the internal boundary to create the cut extrusion. Only one boundary can be used for an Extrude cut so you do not have to right click to end the boundary selection.




Because we want a through cut the exact extrusion distance is not important. Move the mouse pointer up until the extrusion preview is above the part, and click to make the extrude cut.



Right click to end the Extrude Cut command.



Click on the Display icon and change the display mode back to Normal.



To see how you can create a section view of your model, open the Section Tool topic in OneCNC Help.


You can find the topic in Help Contents -> CAD Drawing and Modeling -> Modeling Tools -> Section Tool.

OneCNC CAD Tutorial 4


Working With Planes

All new line and arc geometry, and surface and solid models, are created in the current construction coordinate system, which is independent of the world coordinate system.


When you open a new file in OneCNC, the current construction plane is the XY plane. The X and Y axes of this plane coincide with the X and Y axes of the world coordinate system.



A transparent rectangle indicates the position and orientation of the XY plane of the current construction coordinate system. The Origin selector at the right of the Status bar shows World coordinate input is active.




Clicking on the Origin selector will activate Plane coordinate input. A plane origin indicator will appear.




As an introduction to Plane functions we will position a Plane as an aid to constructing a truncated wireframe pyramid.

Step 1: Draw a pyramid wireframe

Start a new file, and save it as 'Cad Tutorial 4'.




Select World coordinate input, and use the Rectangle command to draw a square from X0 Y0 to X100 Y100.




Start the Line command, and click on the corner of the square to start the first edge of the pyramid.

coordinate	
	World : On plane :
X-Coord	<input type="text" value="50"/> <input type="text" value="50"/>
Y-Coord	<input type="text" value="50"/> <input type="text" value="50"/>
Z-Coord	<input type="text" value="100"/> <input type="text" value="100"/>
<input checked="" type="checkbox"/> ok + Inc	

Enter World coordinates as shown to end the edge at the vertex of the pyramid.



Click on an adjacent corner of the square to finish the second edge of the pyramid.




Right click to end the current Line sequence, and construct the other two edges by clicking on corner, vertex, and corner.
Right click twice to end the Line command.

Step 2: Position the plane



Open the Planes dialog by clicking on the Plane icon in the Status Bar.



In the Planes dialog you will see the XY Default Plane is selected in the Saved Planes list.


You will also see the pre-defined YZ and XZ planes.

The Display active plane check box must be selected for the plane to be visible.





Click on the Push or Pull Plane icon in the Planes dialog.

This command will move the current plane up or down along its Z axis.



Enter a drag amount of 50, and click OK.

The plane will be moved vertically by 50mm.



Click on the Origin selector to activate plane coordinates. The Plane origin indicator shows the origin of the moved plane.


We will now tilt the plane on its own Y axis to create the angle for truncation of the pyramid



Click on the Plane icon again to open the Planes dialog.




Click on the Rotate Plane icon.



The plane can be rotated around the World axes or its own axes.

To rotate the plane around its own Y axis, enter 15 in the Plane Y tilt entry box and click OK.




The plane is tilted on its own Y axis. The plane origin will still be directly above the World origin.

We will save this plane position so we can return to it easily.


Step 3: Save the plane position




Click on the Plane icon again to open the Planes dialog.



Click on the Save icon.



Name the plane Truncation plane and click OK.




The plane now appears in the Saved Planes list.

Step 4: Create the truncated pyramid




To truncate the pyramid edges, open the Trim menu in the Toolbox, and click on the Trim to plane icon. This command trims lines or arcs which pass through the plane to the plane intersection.




Click on an edge of the pyramid, between the base and the plane.

The edge will be cut off where it meets the plane. Click on the next edge to trim it.




The edge will be cut off where it meets the plane. Click on the next edge to trim it.




Continue until all four lines are trimmed to the plane.

When you have trimmed all four side edges of the pyramid, use the




Line command to join them. These lines form the boundary of the truncation.

Step 5: Return to default XY plane




To return to the XY plane, open the Planes dialog and select the XY plane in the Saved Planes List.

To return to World coordinate input, clear the Use plane coordinate system check box before clicking OK.



You will see the XY plane is current again.



You can return to the truncation plane by selecting it in the Saved Planes list.


To learn more about plane commands in OneCNC, go to 'Construction Planes' in the CAD section of OneCNC Help.

OneCNC Technical Drawing

Automated 3D to 2D Drawing Layouts

This tutorial is intended for Expert versions of OneCNC, and Solid Creator.

Automated 3D model to 2D CAD drawing is a standard feature of OneCNC Solid Creator and OneCNC Expert versions, and can be added as an optional module to OneCNC Mill Professional.



Traditionally, a technical drawing was the first step in production of a part. Now, you can design the part as a 3D model, and create one or more technical drawings automatically from the part.

The paperspace drawings are associated to the model, so if the design changes, you can change the part model and then update the drawing views automatically to show the revised part.


There are two stages to creating a technical drawing in OneCNC. The first step is to create a drawing page layout with title block and border. You can then create and manage views of your model in the layout.

Add a drawing page with border and title block




To add a new page, click on the Pages icon in the Status Bar.

The Page Manager dialog will open.




Click on the Add page icon to open the Page Setup dialog.



Templates are supplied for standard paper sizes with pre-drawn borders and title blocks. Select a template for the paper size you want from the Templates list, and enter a name for the page.

The Auto fill template section contains entries which can be automatically added to your title block. Fill these out as necessary, and click OK.




The new page now appears in the Pages list in the Page Manager.

The selected page will be seen in the main drawing window, with the title block showing the details input in the Page Setup dialog. You can now place views from the Views list into the new page.

To return to the main drawing environment, select Model Space in the Pages dialog.

Add views of the model to a drawing page layout


You can add a view of the model to an existing drawing page layout at any stage of the design process.




In the Pages list of the Page Manager, select the page layout you want to add the view to.

Select the view in the Views list, and a preview of the view will appear in the lower section of the Page Manager dialog.

Click the Place view on page icon to add the view to the page.




The view will be attached to the cursor. Click to place the view when it is in the position you want.




After placing the view, you are returned to the Pages Manager again, and you can continue placing views as necessary.

Views are not restricted to orthogonal representations. An Isometric view gives a good indication of what the part actually looks like.



You can create a section view in the Views list using a plane positioned where you want the section.

You can also use a plane to define a view from a specific direction.



Views and section views can be dimensioned as necessary to complete the drawing.

Using the 3D to 2D Technical Drawing module you can quickly create professional drawings to recognized standards. For more detail on using the module see the Automated 3D to 2D drawing topic in the CAD section of OneCNC Help.

OneCNC Mill Tutorial 1


Creating a Facing toolpath

This tutorial is intended for all levels of OneCNC Mill.

To make a part in OneCNC it is first drawn, modelled or imported. The required toolpaths are defined using the NC manager, and simulated to check them. They are then output to an NC file, ready to send to the machine.

We will open a sample file which has machining already defined, and begin to define alternate machining in a new toolpath group.

Step 1: Open the sample file and save a copy.




Sample files are supplied with OneCNC which provide examples of parts and toolpaths.




Click on the Open icon at the top left of the OneCNC application window.

To open a OneCNC sample, go to the Samples folder, which is located in the Drawings folder where you installed OneCNC.




Scroll down the list of files, select the file 'spacer block.ONECNC', and click Open. Select Save As from the File menu, and save a copy of the file as Tutorial Mill 1.ONECNC.




Open the Plane dialog and turn off the display of the active plane. Press the Spacebar and select Trimetric from the View menu. Turn off display of the Geometry layer. Your view screen should now appear as shown.

We will now simulate the existing toolpath group so you can see how each toolpath contributes to the creation of the part.




The NC Manager tab is shown at the right of the drawing window. Right click on the existing Toolpath Group #1, and select Simulate/Rest from the context menu.



The Solid Verification dialog opens, so you can define stock size and other options.

In the Stock panel, choose the Extents option and make sure the Automatic Offset check box is not selected.

-2. Set End X to 155 and End Y to 105. Set Z Top of Job to 0, and Z Bottom of Job to -38.1.



The Live Simulation window will open, and you can watch the toolpaths cutting away the material. The current coordinates of the tool are displayed in the top right corner.

The Live Simulation window has simple playback controls.



Go back to start of simulation.



Go back to the start of the previous tool.



Pause. This changes to Play when paused, which will resume the playback.



Enter simulation Step Mode.




Skip forward to the start of the next tool.



Go to end of simulation.



Turbo mode enables rapid simulation at lower resolution.




You can adjust the playback speed of the simulation by dragging the indicator in the sliding speed control.




You can select a specific playback speed using the drop-down selector below the sliding speed control.

For example, if you select x2 the playback will be twice as fast. If you select /2 the playback will be at half the speed.




During simulation, the progress indicator in the progress bar moves from left to right. The background color of the progress bar changes to match the current tool. You can change the playback position by dragging the progress indicator in the progress bar.


The toolbox on the left of the simulation window has view and display controls. It also holds useful functions for checking your toolpaths.



The view tools allow you to change your viewpoint and zoom magnification.




The Rest material functions are used to check for material which has not been removed yet.




The Display options can be used to show or hide the tool, holder, stock, backplot, and geometry.


If you are simulating a multi-axis toolpath you can also change the axis simulation mode.



During simulation you can check for rapid moves hitting the stock. You can also check for collision between the shank or holder and the stock.




The Options icon re-opens the stock settings dialog.



When the simulation ends the simulation window remains open. Close the simulation window when you are ready to return to OneCNC.



Step 2: Prepare for machining

Imagine you have been sent this part to make. Before you begin to create toolpaths you need the answers to some basic questions. How big is it? How deep is the pocket? What size are the bolt holes? We will extract edges from the model to answer these questions.




Click on the Layer tab in the pane below the NC Manager. The geometry used to create the block is on the Geometry layer, and the block is on the Model layer.


Click on the + icon to create a new layer, and name the new layer Extracted edges. Select the Extracted edges layer as the active layer.



Click on the Model Tools icon in the Toolbox, and click on the Extract model edges icon in the Model Tools menu.




Select the model to extract the edges from it.



Turn off the Model and Geometry layers and you will see the extracted edges.



Click on the Verify tab in the pane below the NC Manager. Click on the Verify Single Entity icon in the Verify toolbar.



By clicking on various lines, and reading the sizes in the Verify panel, you will soon see we are dealing with a part designed in inch measurements.

This is not a problem, as OneCNC toolpaths are based on the existing geometry, we just need to find the depths to enter when we are creating the toolpaths.

The block is 38.1mm (1½") thick and the pocket is 25.4mm (1") deep. The bolt holes have a diameter of 12.7mm, and the counterbores are 12.7mm deep. Across the flats, the edge chamfers are 2.54 mm.



Right click when you are ready to end the Verify command.




Click on the Display icon in the Status Bar to open the Display options dialog.




No frame


Select the No frame option, which will turn off display of surface edges.



Turn off the Extracted edges layer, and turn on the Geometry and Model layers. You will see the basic outlines the part has been constructed from. These outlines are in fact all the geometry we need now to create toolpaths for the complete job.



To make a new Toolpath group, right click in the NC manager panel and select New Group from the context menu.





Double click on the new group and rename it 'Practice Toolpath Group' in the Description box of the Process dialog.


Click OK to close the Process dialog. The new group will now be the active group new toolpaths are created in.

Step 3: Facing toolpath


We will start this example by using a facing toolpath to clean the top of our stock to Z0.



To begin the facing toolpath wizard, click on the Stock Toolpaths icon in the Toolbox, and click on the Facing icon.




The cursor changes to the word bound, and the selection box will cling to the nearest geometry. Hover the cursor near the outside boundary and click to select it.



The selected boundary will turn red and the cursor will cling to the next boundary it finds, as it is possible to face more than one region in the one operation.




As we are only facing the one part, right click to end the selection process.



The Select Tool dialog appears, showing a preview of the last selected tool and holder. If there was no holder associated with the tool, a generic holder with a blue taper will be shown.


We can now select the tool we want to use from the Tool Changer Library, the OneCNC tool management system in which you can store definitions for all the tools you use.




Click on the Tool Changer icon to open the Tool Changer.




At this stage we will only describe how to select a tool from the Tool Changer. A detailed description of how to use the Tool Changer and manage tool definitions in the Tool Library system will be found in OneCNC Help > OneCNC Mill > Mill Common CAM settings.




The Tool Changer dialog opens, with the Recent tab active. Tools you use regularly can be selected quickly from this tab.




To select a tool which is not shown in the Favourites list, click on the Library tab to see a categorized display listing all available tools.



The Tool Library is composed of separate lists for each category of tool. Each row in a list stores information for a single tool. Click on the Facing tool icon at the left of the dialog, and the displayed list will change to show available Face Mill tools.



Select the 50mm Face Mill by clicking anywhere in the row for its listing, and click OK to return to the Select Tool dialog.




The selected tool will be previewed in the Select Tool dialog, with its associated holder, which is defined in the Tool Library. In this case the holder and tool have the same outer diameter.

Enter 6 for the tool number, which is the station on the machine the tool will be in. Set Coolant to No 1 and Work Offset to G54, using the drop-down lists.

Leave the Spindle speed and feedrates as they are, as these will be calculated automatically when we select our material stock.

Tool No.	6
Length Offset	<input type="checkbox"/> 6
Diameter Offset	6
Spindle Speed	0
Coolant	No.1
Work Offset	G54
Feedrate	0
Plunge Rate	0
Adjust high feedrate	<input type="checkbox"/> 0

The stock material is selected from the Material List, which is accessed by clicking on the Stock Material name in the lower part of the Select Tool dialog.



The material definition contains cutting speed information for various types of tool, and this is combined with the tool data to calculate the feedrates and spindle speeds.

Select Aluminium Billet from the material list.


In the lower left corner of the dialog, ensure the check box for Calculate spindle and feed from material is checked.

Select the check box for Feed rounding, which will cut any decimal point value from the calculated feedrate, and click Accept to continue.



We will only describe how to select a material from the Material List at this stage. A detailed description of the Material List and how to manage material definitions will be found in OneCNC Help > OneCNC Mill > Mill Common CAM settings.

You will see the entry boxes for the Spindle Speed, Feedrate and Plunge Rate highlight in yellow as they are updated automatically.



The screenshot shows the 'Facing' software window with the 'Select Tool' dialog box open. The 'Feedrate' and 'Plunge Rate' fields are highlighted in yellow. The 'Spindle Speed' field is also highlighted in yellow. The 'Tool No.' is 6, 'V1' is None, 'Length Offset' is 6, 'Diameter Offset' is 6, 'Spindle Direction' is CCW, 'Coolant' is No.1, 'Work Offset' is G54, 'Feed Control' is checked, 'Adjust high feedrate' is 290, 'Holder' is 22-20 FACE MILL ADAPTOR, 'Tool Type' is Face, 'Overall Length' is 40, 'Flute Length' is 3, 'Diameter' is 50, 'Name' is 1: Pocketing, 'Stock Material' is Aluminium Billet, and 'Notes...' is empty.


The Tool settings are now complete, and we are ready to proceed. Click Next to continue defining the facing operation.



Plunge Rate by default is 50% of the Feedrate. To change the percentage, type the percentage with the % symbol in the Plunge Rate box and that will be the new default.

The Clearances dialog is for entering the Z values we want to use.

You will see the model with frames that indicate the current depth settings.



Start and Finish Clearance is shown as orange corners if enabled. It provides extra clearance before and after an operation. This is mainly used for multi-axis machining, while the part is repositioning.

Enter 5 for Rapid Z Plane. The red frame shows the height the cutter will make positioning moves at.

Plunge Clearance is shown as black corners. It is the incremental distance above the material top at which the plunge move changes from rapid to feed speed, and must be a positive value. Set this to 1.

Enter 1 for Material Z top. For a Facing operation this is the thickness of material to be removed above Z0. Final Z is our Z reference for the job, so set this to 0.

Material Z Top and Final Z are the limits of the range that will be machined, and are both shown as blue frames.

Click Next when these settings have been made.

You will then see the Face dialog, which controls how the facing is carried out.

Facing

Templates :

favourites

history

Face

Facing Parameters

Approach distance : 110 % of tool radius

Overlap amount : 50 % of tool radius

Toolpath Angle : 0

Tool stepover amount

☒ Auto Stepover : 75 % of Diameter

Stepover distance : 37.5

Toolpath Type

☐ Spiral

☒ Zigzag

☐ One Direction

< Back


✓ Finished

✕ Cancel

Select the Zigzag strategy for Toolpath Type.

Approach distance is the lead-in distance as a percentage of the tool radius. Set this to 110 so the plunge to the cut level occurs off the job. Enter an Overlap amount of 50. The tool will travel this far past the selected boundary on each linear pass. Leave Toolpath Angle at 0. This setting can be used to change the angle of the facing passes relative to the X axis.

Select Auto stepover, enter 75 for the % of diameter value, and click Finished.



The new toolpath is created, and an instant preview will be displayed in the drawing window.

The Facing toolpath operation appears under the Practice Toolpath Group heading in the NC Manager.

When the operation is selected, you will also see a summary of the toolpath settings in the lower section of the NC manager.

Some of these settings can be edited directly from the NC manager, simply by clicking on the entry. Click on the Rapid clearance and change the setting to 10. Click on the tick icon to accept the new setting.

NC Manager	
Tutorial Mill 1	
+ Toolpath Group #1	Default post on
- Practice Toolpath Group	Default post
1:Facing	on
50 MM CARBIDE FACE MILL	
Tool diameter	50 mm
Tool tip radius	0.5 mm
Material top	Z1
Max cut depth	1 mm
Final Z clearance	10
Rapid clearance	10
Station number	6
Length offset	6
Diameter offset	6
Spindle Speed	1114
Coolant	No.1
Work offset	G54
Feedrate	290
Plunge feedrate	145
High feedrate	None

To simulate the new toolpath, right click on the operation in the NC manager, and select Simulate/Rest from the context menu.

NC Solid Verification

Stock

☒ Extents (default)
☐ Stock Model
☐ Pick a boundary


☐ Automatic Offset: 0
 Z Top of Job: 1
 Z Bottom of Job: -38.1

☐ Turbo Mode
 Start X: -2 End X: 155
 Start Y: -2 End Y: 105

OK Cancel

In the NC Solid Verification dialog, set Z Top of Job to 1, so you can see the stock being machined to the Z reference height.

Click OK to continue.



The simulation appears, showing the stock being faced back to the Z0 level.

Select the Show geometry icon in the toolbar at the left of the simulation window and the geometry outlines will appear.

Close the simulation window when you have observed the toolpath.

In Mill Tutorial 2 we will complete the toolpaths for this part.



To see how the other facing strategies work, right click on the Facing operation in the NC manager list, and select Edit operation. The toolpath wizard will re-open. Click Next on the Tool and Clearances pages without changing any settings.

When you get to the Face options dialog, select one of the other strategies and click Finished. Simulate the operation again to see how the toolpath has changed.

OneCNC Mill Tutorial 2



Stock Toolpaths

Stock toolpaths - Pocket, Profile and Chamfer


This tutorial is intended for all levels of OneCNC Mill.

This tutorial continues the toolpath group started in Mill Tutorial 1. Open the file you used for that tutorial, and save a copy of the file as Tutorial Mill 2.ONECNC.

Step 1: HS Pocketing toolpath




To begin the pocketing toolpath wizard, click on the Stock Toolpaths icon in the Toolbox, and click on the HS Pocketing icon.



The cursor changes to the word bound, and the selection box will cling to the nearest geometry. Hover the cursor near the inside boundary and click to select it. The selected boundary will be highlighted and the cursor will cling to the next boundary it finds, as it is possible to pocket more than one boundary in one operation.

We have only one pocket operation to do, so right click to end the selection process.



When the Select Tool dialog appears, click on the Tool Changer icon to open the Tool Changer dialog.


In the Favourites list you will see the 20mm bullnose cutter which is already in use in this file. Select it and click OK to return to the Select Tool dialog.

Enter Tool Number 1, set Coolant to No 1 and Work Offset to G54.

Select Aluminium Billet from the Material List.

Select the Adjust high feedrate check box, and enter a value of 5000. When the toolpath has to reposition inside the pocket, this will be done at the high feed rate without retracting if it is possible to do so.

Click Next to continue.



The Clearances dialog for entering the Z values is similar to that used in the facing operation.

Clear the check box for Start and Finish Clearance, as we do not need it for this job.


Enter 5 for Rapid Z Plane. This is the height the cutter will retract to between plunges during the operation.

Plunge Clearance is the distance at which the plunge changes from rapid to feed speed as it approaches the Material Z Top. Set this to 2.

Material Z Top is our Z reference for the job, so set this to 0.

Set Final Z to -25.4, the depth of the pocket.

Click Next when these settings have been made.




By clicking on the options in the Machining Style dialog, you will see a preview showing the types of toolpath they produce.

Traditional is the method which follows boundary offsets.

Highspeed - Open is used when machining from an outside stock shape to an internal boundary.

For this part, select the Highspeed - Closed Toolpath option for the machining style, and click Next.



The settings in the next dialog control the entry of the tool into the job.

Plunge entry is usually used for Highspeed Open toolpaths, as the tool can plunge down to Z level beside the part. For a Highspeed Closed toolpath, helix entry is the preferred option.

Select Ramp Helix for the toolpath entry style, and enter a Ramp angle of 10 degrees. Set the Helix Diameter at the maximum 20.

Select Automatic entry position, and click Next.

Pocketing

Templates :

favourites

history

Rough settings

Auto stepover ☒ 25 % of diameter

Stepover distance : 5

Rough depths ☐ 0

Finish Leave on sides : 0

Leave on bottom ☐ 0

Tolerance : 0.005

Wall taper : 0

< Back

> Next

X Cancel

In the Rough settings dialog, stepover is the width of the cutting path. Select Auto stepover and set it to 25% of the tool diameter.

When enabled, the Rough depths value is a positive number defining the depth increment for each roughing pass. Clear the check box for Rough depths as the tool we are using can cut the pocket in one pass.

Set Leave on sides to 0 as we are not doing a finish cut. Set Tolerance to 0.005 and Wall taper to 0, and click Next to continue.


HSM Settings

The traditional pocketing method typically uses a stepover close to the tool diameter, with a rough depth equal to or less than the tool diameter.

The HSM toolpath was developed to use the flank of the tool to progressively side mill material from the remaining stock. HSM machining can use depth of cut up to 2 x tool diameter if stepover is reduced to 30%. This strategy is faster and needs less than 50% of the average power required for the traditional method.


Page 134

Introduction to OneCNC Mill ©



It is possible to define Rough settings and Finish settings in one operation. If you set a Leave on sides amount in the Rough settings, you can define Finish pass settings in the Finish Settings dialog.

We will use Finishing in the next toolpath, but for this operation leave Finishing set to None. Click Finished to create the toolpath.



Click on the new toolpath in the NC manager, and you will see a preview of the toolpath in the drawing window.

Step 2: Mill Profile toolpath

To cut the outside of our part, we will create a Mill profile toolpath.




Stock Toolpaths




Mill profile

Click on the Stock Toolpaths icon in the Toolbox, and click on the Mill profile icon.




Click on the outside boundary to select the start of the chain.

Four side and direction indicator arrows will appear.



The arrow closest to the cursor will be highlighted red, indicating the current side and direction for the toolpath. Hold the cursor so that the arrow outside the boundary and pointing to the left is red, and click to confirm the side and direction.



Select the last entity in the profile to cut, or press F3 to automatically select to the end of the chain.

Right click to end the selection process.


Mill Profile

Templates :

favourites

history

Select Tool



Tool No.

2

V1 None

Length Offset

☐

2

V2 None

Diameter Offset

2

V3 None

Spindle Speed

1527

V4 None

Spindle Direction

☒ CW

☐ CCW

☐ CW

Coolant

No.1

Work Offset

G54

Feedrate


800

Feed Control

Plunge Rate

400

Tool Changer



Holder

32 MM SIDELOCK

Tool Type

End

25 MM HSS END MILL

Overall Length

80

Flute Length

☒

45

Diameter

25

Name :

3.Outer Mill Profile

Stock Material

Aluminium Billet

Notes...

< Back

> Next

✕ Cancel

Click on the Tool Changer icon and select the 25 MM HSS END MILL tool.


Enter Tool Number 2, set Coolant to No 1 and Work Offset to G54.

Select Aluminium Billet from the Material List, to update the Feed and Speed settings.

Click Next to continue.

Introduction to OneCNC Mill ©

Page 137




In the Clearances dialog, we need to enter the Z depth values for this operation.

Enter a Rapid Z Plane clearance of 5, with a Plunge clearance of 1.

Set Material Z Top to 0.


The block is 38.1 mm deep. Enter a Final Z of -38.3, so the cutter goes a little below the edge of the block.

Click Next to continue.



The Path Creation dialog gives you the option of machining the profile by horizontal levels or as a continuously descending ramp.

Select the Cut Levels option and click Next to proceed to the Roughing settings.



In the Rough settings dialog, select Auto stepover and set it to 75% of the tool diameter.

Select the Rough depths checkbox, and enter a value of 19.5.


Enter 0.2 in the Leave on sides box, this is the amount the rough pass will leave for finishing.

Clear the check box for Remove amount, as we do not need to remove extra material with horizontal offsets.

The sides are vertical so set Wall taper at 0.

Clear the check box for Last cut. This can be used to specify a specific increment for the last cut when breaking through material.

Click on Next when you are ready to continue.



When the Finish settings appear, select Bottom only from the drop-down list for finishing, so there will be a finish pass after the last roughing pass is complete.

Select Automatic from the dropdown list for the cutter radius compensation method. OneCNC will write the NC file with the appropriate offset for the selected tool. If you want to use G41 or G42 on your machine, you would select the "at Control" option.

The rough settings we defined will have the cutter make a roughing pass at Z-19.5 and then at full depth, with 0.2 offset each time.

The Bottom only Finish setting means there will then be a finish pass on the geometry at full depth.

Click Next to continue.

Mill Profile

Templates :

favourites

history

Entry and exit for finishing

Leadin style : Line-Arc

Leadout style : Line-Arc

Overlap amount ☐ 0

Entry values :

Leadin Radius 5

Leadin Angle 135

Start Line Length 5

Start Line Angle 0

Exit values :

Leadout Radius 5

Leadout Angle 135

End Line Length 5

End Line Angle 0

Back

Finished

Cancel

In the Entry / Exit dialog, we will enter the variables which control leadin and leadout.

Use the drop down selectors to set Leadin and Leadout style to Line-Arc.

Enter a Leadin Radius of 5, and Leadin Angle of 135.


Enter a Start Line Length of 5, and a Start Line Angle of 0.

Click on the arrow button above the Exit values to copy the Entry values to the Exit values.

Click Finished and the Mill Profile toolpath will be created.

Page 142

Introduction to OneCNC Mill ©



Simulate the new toolpath and you will see the cutter roughing and finishing the profile. When the cutter finishes the first roughing pass it will feed down and cut the second roughing pass. It will then retract before repositioning to begin the finish pass.

Close the simulation and we will continue with the Chamfering.

Leadin/Leadout



The leadin-leadout settings used create a teardrop shaped toolpath which starts and stops at the same point for the rough passes.

This means the cutter is allowed to plunge to the second rough depth without retracting to the rapid plane.

The toolpath will retract to the rapid plane when the cutter has to reposition to start the finish pass.

For safety, OneCNC always retracts the tool before repositioning.

Step 3: Chamfer toolpath

We will now use a Chamfer toolpath to chamfer the pocket and outside edges in one operation. The chamfers on the boltholes will be created as part of the hole feature operation in the next tutorial.




Stock Toolpaths




Chamfer edge

Click on the Stock Toolpaths icon in the toolbox, and then select Chamfer edge from the Stock Toolpaths menu.




Select the outside profile as before. Set the direction as shown and press F3 to automatically select the complete profile.



Click on a start position for the internal profile, and click as shown to set the side and direction. Press F3 to automatically select the complete profile.



When both profiles have been selected, right click to end the selection process.




Select the 12mm chamfer tool from the Tool Library.

Enter Tool Number 3, set Coolant to No 1 and Work Offset to G54.

Select Aluminium Billet from the Material List, to update the Feed and Speed settings.

Click Next to continue.



In the Clearances dialog, the only entries required are those for Rapid Z Plane, which we will set to 5, and Plunge clearance, which we will set to 1.


The Z depth of the chamfer cut is not required in the Clearances dialog, as this will be calculated automatically in the next step of the toolpath definition.

The depth is determined relative to the selected geometry.

Chamfer Depth



If the geometry you want to use is not at the required Z level, you can use the Z Position option of the Smart Projection command in the Model menu to move or copy it.




Our outline is at the intersection of the top surface and side of the part, which is marked by the number 1 in the diagram, so we will select 1. Normal for Geometry Position.

Select the check box to set Tip Z to auto. This modifies the cutter travel so the cutter flute is centered on the chamfer flat, with the tip below and outside the profile.


The Length and Width boxes refer to the length across the chamfer surface, and the horizontal width of the chamfer.

On our model, the edge chamfers are 2.54 mm (0.1") across the chamfer, so enter 2.54 in the Length box. The Width box will update to 1.796, the horizontal width of the chamfer.

The Length and Width boxes are linked, and each can update the other. If you enter the horizontal width of the chamfer in the Width box, you will see the length across the chamfer calculated.



The Entry / Exit conditions can be set exactly as used for the Mill Profile toolpath.



Click Finished, and the Chamfer toolpath will be created.

OneCNC Mill Tutorial 3


Hole Feature Recognition

This tutorial is intended for all levels of OneCNC Mill.


In this tutorial we will complete the toolpath group started in Mill Tutorials 1 & 2. Open the file you used for Mill Tutorial 2, and save a copy of the file as Tutorial Mill 3.ONECNC.

Step 1: Hole Feature selection

Hole Feature Recognition is a time saving method of creating all the drilling and machining commands for a set of holes in one operation.




Click on the Stock Toolpaths icon in the toolbox, and then select Drill Hole Wizard from the Stock Toolpaths menu.




The Hole Wizard will open with a window containing a browser list of all the hole features found in the current window.

Select the check box for the simple hole group and the four holes in the group will be selected automatically.




When you have selected the holes, click Next to proceed to the Clearances dialog. Set the Rapid Z Plane at 5, Plunge Clearance to 1 and Material Top to 0. Click Next to continue.




On the left of the Settings dialog is the Hole Operations list, where you can define multiple operations to apply to the selected holes.

The list of operations can be saved as a Hole Definition.

Step 2: Drill Operation




Click on the Drill icon and a new drill operation will be added to the Hole Operations list.



Right click on the operation and choose Edit 'Drill' from the context menu.

Drilling Cycle

Select Tool



Tool No.

4

V1 None

Length Offset

☐

4

V2 None

Diameter Offset

4

V3 None

Spindle Speed

3007

V4 None

Spindle Direction

☐

CCW

☒

CW

Coolant

No.1

Work Offset

G54


Feedrate

108

Plunge Rate

54

Tool Changer



Holder

12 MM KEYLESS DRILL CHUCK

Tool Type

Drill

12MM DRILL, 118 INC

Overall Length

80

Flute Length

☒

37

Diameter

12

Included angle

118

Name :

2-C/Bore Hole, 12 MM Bolt

Stock Material

Aluminium Billet

Notes...

< Back

> Next

X Cancel


Each Hole operation is defined in a step by step fashion similar to the Stock toolpaths dealt with earlier.

The first step in defining the Drill operation is to select the 12mm Drill from the Tool Library.

Enter Tool number 4, and set Coolant to No1 and Work Offset to G54.

Select Aluminium Billet from the Material List to set the feedrates and spindle speed.

Click Next to continue.



In the cut Parameters dialog there are a number of methods available to create the hole. Select Automatic drilling, which is the setting for OneCNC to create the drilling cycle.

Set Depth Style as Absolute, and enter -38.2 for Final Z, a little below the bottom of the part. The tool depth is measured at the point of the drill, so this setting alone would not drill the hole completely.

Select the Drill Through check box, which enables compensation for the point angle. The depth value will now be -42.015, which will put the edge of the drill past the base of the hole.

Hole Feature Operation Settings




OneCNC can create circular holes by plunge drilling or machining. To learn more about hole feature methods, see the Hole Feature Settings topic in the Mill Hole Features and Drilling section of the OneCNC Help files.

Drilling Cycle

Custom Drilling

Type of Drilling

☐ Standard
☒ Peck
☐ Deep Hole



Drill Settings

Dwell :
 Max Peck Amount :
 Rapid Return Clearance : ☒ 0.5
 Peck Retract :

Retract Speed

☒ Rapid
☐ Feed

Retract to

☒ Rapid Plane
☐ Plunge Clearance

[< Back](#)
[✓ Finished](#)
[X Cancel](#)

When Automatic Drilling is selected, you will see the Custom Drilling dialog when you click Next.


This has options for choosing drilling type and the relevant settings for each type. Select Peck drilling, and set Dwell to 0.

Set Max Peck Amount to 2. OneCNC will calculate the nearest peck distance to drill the hole in regular intervals.

To enable rapid instead of feed moves when returning to depth after each retract, select the check box for Rapid Return Clearance and enter a value of 0.5 to change the rapid return to a plunge feed move 0.5 from the new cut level.


Select Rapid Retract Speed, and Retract to Rapid Plane.

Click Finished to return to the Hole Feature Settings dialog.



Now that the Drill operation is defined, a cross section appears in the preview pane. Next we will add a Counter Bore operation.

Step 3: Counter Bore Operation




Click on the Counterbore icon to add the next operation to the Hole Operations list.


Right click on the new Counterbore operation and select Edit 'Counter Bore'.

Drilling Cycle

Select Tool



Tool No. V1 None
 Length Offset ☐ 5 V2 None
 Diameter Offset V3 None
 Spindle Speed V4 None
 Spindle Direction ☐ ☒ CCW ☒ CW
 Coolant
 Work Offset
 Feedrate
 Plunge Rate

Tool Changer 

Holder
 Tool Type 8 MM HSS END MILL
 Overall Length
 Flute Length ☒ 19
 Diameter

Name :

Stock Material

Notes...

< Back > Next X Cancel

Counter boring is a machining operation, so we need to select a milling cutter.

Select the 8mm carbide end mill from the Tool Library.

Enter Tool number 5, and set Coolant to No1 and Work Offset to G54.

Select Aluminium Billet from the Material List, and click Next to continue.

Drilling Cycle

Cut Parameters

3. Material Top : Z0

Taper Angle

0

4. Diameter

20

Hole Style

Machine Cycle

Automatic Drilling

Profile

☒ Helix

Clean circle

2. Hole Depth

Incremental

Absolute

2. Hole Depth

12.5

< Back

> Next

X Cancel


Select the Helix Hole Style option, which creates the hole by machining down a helical ramp.

Enter 20 in the Diameter box. The diameter of Profile, Helix, and Clean Circle hole features is not determined by the circles selected for center positions, they will be cut to the diameter entered here.

Select Incremental Depth Style and enter a value of 12.5, which is the distance from the selected geometry to the bottom of the counter bore, then click Next.

Page 160

Introduction to OneCNC Mill ©




The entries in the Settings dialog determine how the helical machining will be carried out.

For this operation, enter 0 for the Leave for finish value, as we will not be doing a finish pass.

Enter a value of 2 for the Depth per turn. This setting is the pitch of the helical ramp, so the cutter will descend at 2mm per revolution.

Select the Climb milling option for the Direction of Cut.

Click Finished and the Counter Bore operation will be complete.




The Counter Bore operation now appears in the preview pane.

Operations selected in the Hole Operations list are shown in light blue.
To complete the hole operations, we will chamfer the hole edge.

Step 4: Chamfer Operation


Click on the Chamfer icon to add a Chamfer operation to the Hole Operations list.



Double click on the Chamfer operation to open it for editing.

Drilling Cycle

Select Tool



Tool No.

3

V1 None

Length Offset

☐

3

V2 None

Diameter Offset

3

V3 None

Spindle Speed

7321

V4 None

Spindle Direction

☐

CCW

☒

CW

Coolant

No.1

Work Offset

G54


Feedrate

3514

Plunge Rate

1757

Tool Changer



Holder

20 MM ER COLLET CHUCK

Tool Type

Chamfer

12 CHAMFER

Overall Length

50

Flute Length

☒

4.5

Diameter

12

Tip diameter

3

Taper angle

45

Stock Material

Aluminium Billet

Name :

2C/Bore Hole, 12 MM Bolt

Notes...

< Back


> Next

X Cancel

Select the 12mm Chamfer tool you used earlier from the Tool Changer Favourites list.

Set Coolant to No1 and Work Offset to G54.

Select Aluminium Billet from the Material List, and click Next to continue.




There are three settings in the Cut Parameters dialog for a Chamfer operation.


For this job, set the Diameter to 20. Like the Helix operation, the diameter of the inner chamfer edge is not constrained by the size of the circle selected for its center. The Chamfer will be cut to the size entered, so we must be careful to enter the same value.

Enter a Tip Offset of 1 and set the chamfer Width to 1.5.

Click Next to continue.




In the Path Creation dialog, select Plunge entry and Climb Milling.




In the Settings dialog, set Leave for finish to 0, and click Finished.

The Chamfer operation is now complete, and the complete hole profile is shown in the preview pane.




Before clicking Finished to create the hole feature toolpaths, we will save the Hole Operations list for future use as a Hole Definition. Once saved, drilling and machining for a particular bolt or hole size can be quickly applied in a new part.


Step 5: Saving Hole Operation Settings




Right click in the Hole Operations pane and select Save List from the context menu.



Enter a name for the Hole Definition that you will recognise easily when you need it again, and click OK.



Click Finished to create the toolpaths.



For a fixed display of the toolpath, right click on the Hole operation in the NC manager, and select Backplot from the context menu.

The toolpaths for the hole operations are drawn as geometry in the drawing window, on a new layer named Backplot.

OneCNC Mill Tutorial 4

The NC Manager and Outputting NC files

This tutorial is intended for all levels of OneCNC Mill.

This tutorial will cover toolpath management and NC file output features of the NC Manager, using the toolpaths from your Tutorial Mill 3.ONECNC file. Open the Tutorial Mill 3.ONECNC file and save a copy as Tutorial Mill 4.ONECNC.

NC Manager Groups and Operations

When you create a toolpath in OneCNC, it is created in the active Toolpath Group, which is highlighted in the NC manager.

By right clicking an operation or group you can use the NC Manager context menu to select various functions. The toolpath order can be changed by dragging toolpaths into new positions.

When a toolpath is selected, it will be previewed in the drawing window, and the current settings will be displayed in the settings pane below the toolpath pane.

Many toolpath settings can be changed directly in the settings pane.


NC Manager	
Tutorial Mill 4	
+ Toolpath Group #1	Default post on
- Practice Toolpath Group	Default post
1:Facing	on
2:Mill Pocketting	on
3:Mill Profile	on
4:Chamfer	on
5:Combo Hole, 12.707mm bolt, Z-12.	on

50 MM CARBIDE FACE MILL	
Tool diameter	50 mm
Tool tip radius	0.5 mm
Material top	Z1
Max cut depth	1 mm
Final Z clearance	10
Rapid clearance	10
Station number	6
Length offset	6
Diameter offset	6
Spindle Speed	1114
Coolant	No. 1
Work offset	G54
Feedrate	290
Plunge feedrate	145
High feedrate	None


Duplicate an operation

In the Practice toolpath group the 12mm chamfer tool is used twice. Because the chamfer is the last operation in the Hole Feature definition, we can eliminate the need for a tool change by putting the Hole Feature before the Chamfer operation.

Before making any changes we will make a copy of the Practice group. Right click on the Practice Toolpath Group name bar, and select Duplicate Group from the context menu.




A duplicate Toolpath Group is created beneath the Practice group. The Practice Toolpath Group is still the active group.




Click on the - symbol at the left of the Practice Toolpath Group to contract it.

Click on the + symbol at the left of the new group to expand it.





Right click on the Duplicate group name bar, and select Activate Group from the context menu.

The duplicate group name bar will be highlighted, indicating it is now the active group.




To move an operation

Select the Hole Feature operation and move it up by holding the left mouse button down on the operation name and dragging it to its new position, above the Chamfer operation.




Simulate the duplicate group and you will see all the chamfering now happens at the end of the program.

The NC Processing dialog



Select the Duplicate of Practice Toolpath group, and click on the Process icon at the top of the NC Manager. This opens the Process dialog which has controls and tools for Post-processing your program.



The left side of the Process dialog has icons for many of the functions which appear in the NC Manager right click context menu.

The text fields in the Process dialog allow input of information that can be included in the NC program.

A toolpath or group can be turned on or off for simulation and output using the Status selector.


Change the Description to Edited Toolpath Group.

When we moved the hole feature operation, the operation numbers were no longer in sequence. Click Renumber operations to renumber the operations in the group.

NC Code output

OneCNC formats the NC file as it is output, to suit the varying requirements of different makes of CNC machines.


The format setting is called a 'Post', which is short for post-processor. OneCNC is supplied with a comprehensive set of prepared Posts for most machines in use.



Click on the drop down list to select the Post for your machine.



Click on the Post icon to output the NC program.




The Save As dialog appears. Choose the directory to save the file to, and enter a name for the file. Select the file type from the Save As type: list and click Save.



A Post can be customized by clicking on Setup to open the NC Post Settings dialog.

See the 'Mill NC Post and DNC Settings' in the OneCNC Mill CAM folder in the Help files for guidance on this advanced subject.



Your NC file opens in OneCNC Link, which is an independent text editor and RS232 communications program.

When you first start using OneCNC you should check through the output to make sure it is formatted the way you want for your machine. You will post and send files with confidence once your format is proven.



To send the file to your machine, click on the Send icon on the OneCNC Link Standard toolbar to open the communication dialog for your machine.



Comprehensive information on how to use the OneCNC Link NC Editor, and setup communications, is available in the OneCNC Link Help files. The editor includes the standard text editing tools such as Find and Replace, and has a convenient machining calculator for feed and speeds.

As well as sending files to your machine, OneCNC Link can be used to type parametric programs or receive and archive programs which may have been edited at the machine controller.

Post Settings: Start And Finish Format

```
%  
O0001  
N10 (PART - 001)  
N20 (FILE - D:\ONECNC\MILL 4.ONECNC)  
N30 (AUTHOR - DEFAULT USER)  
N40 (GROUP - SPACER BLOCK)  
N50 G00 G40 G49 G80  
N60 G00 G90 G54
```

An NC program will start with initial information such as a program number, default G and M codes, and text comments in () brackets for the operator. This section is defined by the Start lines of the Start and Finish Format.

```
N30 G00 G17 G40 G49 G80 G90  
N40 (50 MM CARBIDE FACE MILL)  
N50 T6 M06  
N60 G00 G90 G54 X-24.764 Y3.325  
N70 S0 M03  
N80 G43 H6 Z10.  
N90 M08  
N100 G00 X-24.764 Y3.325 Z10.  
N110 Z1.  
N120 G01 Z0. F0.0  
N130 X-8.302  
N140 X164.9  
N150 Y34.975  
N160 X-12.5  
N170 Y66.625  
N180 X164.9  
N190 Y98.275  
N200 X-8.302  
N210 G00 Z10.  
N220 M09  
N230 (END TOOL)
```


The output from each toolpath operation will consist of code lines for a toolchange defined by the Tool Format Start Lines, and then the movement of the tool defined by the line and arc movement formats. The operation will end with the Tool Format End Lines.

```
N18920 G91 G28 Z0.  
N18930 G91 G28 X0. Y0. M05  
N18940 M30  
%
```


Toolchanges and operations continue as required. After these instructions, there will be an end of program section with return to home position and program end codes. This section is defined by the End lines of the Start and Finish Format.

Post settings are managed in OneCNC by the NC Post Settings dialog, which has powerful but easy to use commands for changing how your file is output.


It is important that you understand the NC code for your machine before making changes to an existing post. If you don't know what effect changing a format setting will have, leave it alone as incorrect settings may cause serious damage. For now we will only explain how to add a tool list to the Start lines of the Start and Finish Format.



To create a copy of an existing post and edit it, click on the Setup icon at the right of the Post selector.



The NC Post Settings dialog will open. Click on the New Post icon at the top of the dialog. Enter a name for your new Post and click OK. The new Post will be a copy of the Post that was active when you clicked the New Post icon.




Select the Posting Format tab.



It is recommended that you always create a copy before editing a Post. Editing the new Post will not affect the Post it was copied from. You will have the original Post to refer to if you want to check settings you have changed, and you can revert to the original Post if necessary.


All users must be informed of changes made to a Post.




Select START and FINISH FORMAT from the drop down format list. In the Start Lines - box, you will see lines of text. This is the format for the beginning of every NC program using this Post.


Each block of text in { } brackets represents a variable which will be output in the NC file as the variable value. Text not in { } brackets will be output as is.

On the right side of the Posting Format Tab is a list of the available Substitution variables. Select the Tooling variable.






Click to place the cursor as shown in the Start Lines text box. Click the Insert button to add the Tooling variable to your post format.



The {TOOL_SUMMARY} Tooling variable appears at the cursor position.

Click OK to accept the changes and close the NC Post Settings dialog.

Select the modified Post in the NC Processing dialog, and click on the Post icon to output the NC file.



Specify the file location to save to, and the file will open in NC Link. The {TOOL_SUMMARY} Tooling variable has inserted a list which shows the operator what tools are used and the station they are in.

The {TOOL SUMMARY} writes its own () brackets in the output file, but other variables used in comments must be inside a pair of () brackets in the Post format.

OneCNC Mill Tutorial 5

Stock toolpaths - Cut Chain and Engrave All


This tutorial is intended for all levels of OneCNC Mill.

This tutorial covers the use of the Cut Chain 2D, Cut Chain 3D, Engrave All 2D, and Engrave All 3D toolpaths. These are all toolpaths which follow the defining geometry without an offset.


Cut Chain 2D

This toolpath is used to cut a single entity or chain of entities. The toolpath will ignore the Z-values of the geometry. The tool center will travel along the chain at the Z depth specified. One of the uses for Cut Chain is to create a slot, when you know where the centerline will be.


Save a new file as Tutorial Mill 5, and create a layer named Chain 2D.



Draw a rectangle 100 x 75 with a corner radius of 10, starting at X10 Y10.



Click on the Stock toolpaths icon, and select the Cut Chain 2D toolpath.



Click on the chain where you want the cut to start. Click as shown to set the direction of travel, it doesn't matter which side of the chain you select as the toolpath is not offset.

Press F3 to select the rest of the chain automatically.


Cut Chain 2D

Templates :

favourites

history

Select Tool



Tool No. 1

Length Offset 1

Diameter Offset 1

Spindle Speed 12000

Spindle Direction ☐ CCW ☒ CW

Coolant No.1

Work Offset G54

Feedrate 336

Plunge Rate 168

Holder 20 MM ER COLLET CHUCK


Tool Type End

Overall Length 40

Flute Length ☒ 11

Diameter 4

Tool Changer



Name : 1:Cut Chain 2D

Stock Material Aluminium Billet


Notes...

< Back

> Next

X Cancel


Select the 4mm carbide end mill tool from the Tool Library, and enter Tool No. 1. Set Coolant to No1 and Work Offset to G54. Select Aluminium Billet from the Material List, and click Next to continue.




In the Clearances dialog, set Rapid Z Plane at 5 and Plunge Clearance to 1.

Set Material top to 0 and Final Z at -4.

Click Next to continue.



The Path Creation settings allows you to mill to the full depth in more than one pass. Select the Cut Levels Toolpath style, and enter a Depth of cut value of 2. The toolpath will be cut in 2mm deep increments.





Click Finished to create the toolpath. The toolpath appears as a Cut Chain 2d operation in the NC Manager, and will preview in the drawing window when the operation is selected.

Cut Chain 3D


This toolpath is used to cut a single entity or a single chain of entities. It is similar to Cut Chain 2D, but as well as following the XY values, the toolpath will follow the Z-values of the chain geometry itself.

We will demonstrate Cut Chain 3D on a copy of the Chain 2D geometry, rotated into a 3D position.


Select the slot geometry on the Chain 2D layer by clicking the selection box in the Layers Manager.



Select the Rotate command from the Transform menu.




Select the World origin as the point to rotate around.




Select Copies and enter 1.

Select the Attributes check box to enter the new layer for the rotated copy.



Enter Chain 3D in the Layer entry box.
The layer will be created for the rotated copy.




Enter 15 for the angle of rotation in the
Rotation Y entry box, and press Enter.


This will rotate the selected geometry
about the World Y axis.




Right click to end the Rotate command.




Turn off display of the Chain 2D layer,
and select Chain 3D as the current layer.



The display of the original chain has now been turned off, and the rotated copy is still visible on the new layer.



Click on the Stock Toolpaths icon and select the Cut Chain 3D toolpath.



Pick the start point near the top of the chain, and click to set the direction of cut. It doesn't matter which side of the chain you are on as the center of the tool will travel on the geometry path.

Press F3 to select the rest of the chain automatically.

The Select Tool dialog will appear.

Cut Chain 3D

Templates :

favourites

history

Select Tool

Tool No. 1 V1 None

Length Offset 1 V2 None

Diameter Offset 1 V3 None

Spindle Speed 6000 V4 None

Spindle Direction ☐ CCW ☒ CW

Coolant No. 1

Work Offset G54

Feedrate 168 Feed Control

Plunge Rate 84

Tool Changer

Holder 20 MM ER COLLET CHUCK

Tool Type End 4 MM CARBIDE END MILL

Overall Length 40

Flute Length ☒ 11

Diameter 4

Name: 2.Cut Chain 3D

Stock Material Aluminium Billet


Notes...

< Back > Next X Cancel

Using the Tool Changer, select the 4mm carbide end mill used for the Cut Chain 2D toolpath.

Set Coolant to No1 and Work Offset to G54.

Select Aluminium Billet from the Material List, and click Next to continue.




In the Clearances dialog, set Rapid Z Plane at 5 and Plunge Clearance to 1.


Set Material top to 0.

There is no Final Z entry as the depth is set by the geometry.

Click Next to continue.



The Path Creation settings allows you to mill to the full depth in more than one pass, but for this example select None for the Toolpath style.





Click Finished to create the toolpath. The toolpath appears as a Cut Chain 3D operation in the NC Manager, and will preview in the drawing window when the operation is selected.

Engrave All 2D



The Engrave All 2D function is used to automatically cut all entities visible in the view port at a set Z level

Open the sample file 'Engrave All Variable Z.ONECNC'.
Save a copy of the file as 'Tutorial Mill 5 Engrave All.ONECNC'.

Turn on the 2D Engraving layer, and
turn the other layers off.



You will see the 2D engraving geometry.



Click on the Stock Toolpaths icon and select the Engrave All 2D toolpath.

As all visible geometry is automatically selected for this toolpath, you will see the Select Tool dialog immediately.


Cut All Entities 2D

Templates :

favourites

history

Select Tool



Tool No. 0 V1 None

Length Offset 0 V2 None

Diameter Offset 0 V3 None

Spindle Speed 12000 V4 None

Spindle Direction ☐ CCW ☒ CW

Coolant No. 1

Work Offset G54

Feedrate 72 Feed Control

Plunge Rate 36

Tool Changer

Holder ER20 COLLET CHUCK

Tool Type Engrave 6MM ENGRAVE

Overall Length 40

Flute Length ☒ 5.2

Top diameter 6

Tip corner radius 0

Bottom / tip diameter 0.05 Taper Angle 30


Stock Material Aluminium Billet Notes...

Name: 3.Cut All 2D

< Back > Next X Cancel

Select the 6mm 60 degree engraver tool from the Tool Library, and set Coolant to No1 and Work Offset to G54.

Select Aluminium Billet from the Material List, and click Next to continue.




In the Clearances dialog, set Rapid Z Plane at 5 and Plunge Clearance to 1. Set Material top to 0 and Final Z at -1. Click Next to continue.

An engraving tip




For small text, a single line shx font such as _romans will be clearer and take less time to cut.

When engraving larger text, a bold TrueType font will give a better result as the separation of the outlines is more distinct.



The Path Creation settings allows you to mill to the full depth in more than one pass, but for this example select None for the Toolpath style.





Click Finished to create the toolpath. The toolpath appears as a Cut All 2D operation in the NC Manager, and will preview in the drawing window when the operation is selected.



Engrave All 3D

Like Engrave All 2D, this function is used to automatically cut all entities visible in the view port. Instead of cutting at a set Z level, the Variable Z toolpath will follow the Z-values of the geometry itself. It is often used to engrave text which has been created on, or projected onto, a 3D surface or plane.

Turn on the 3D Engraving layer, and turn the other layers off.



You will see the 3D engraving geometry.



Click on the Stock Toolpaths icon and select the Engrave All 3D toolpath.

As all visible geometry is automatically selected for this toolpath, you will see the Select Tool dialog immediately.


Cut All Entities 3D

Templates :

favourites

history

Select Tool



Name : 1.Cut All 3D

Tool No. 2 V1 None

Length Offset 2 V2 None

Diameter Offset 2 V3 None

Spindle Speed 12000 V4 None


Spindle Direction ☐ CCW ☒ CW

Coolant No.1

Work Offset G54

Feedrate 72 ☒ Feed Control

Plunge Rate 36

Tool Changer 

Holder ER20 COLLET CHUCK

Tool Type Engrave 6MM ENGRAVE

Overall Length 40

Flute Length ☒ 5.2

Top diameter 6

Tip corner radius 0

Bottom / tip diameter 0.05

Taper Angle 30

Stock Material Aluminium Billet

Notes...


< Back

> Next

✕ Cancel

Select the 6mm 60 degree engraver tool from the Tool Library, and set Coolant to No1 and Work Offset to G54.

Select Aluminium Billet from the Material List, and click Next to continue.




In the Clearances dialog, set Rapid Z Plane at 5 and Plunge Clearance to 1.


Set Material top to 0.

There is no Final Z entry as the depth is set by the geometry.

Click Next to continue.




The Path Creation settings allows you to mill to the full depth in more than one pass, but for this example select None for the Toolpath style.



Click Finished to create the toolpath. The toolpath appears as a Cut Chain 3D operation in the NC Manager, and will preview in the drawing window when the operation is selected.


Advanced Stock Toolpaths

Thread Milling



Thread Milling is an efficient means of cutting a thread, especially for larger diameters. With a single tip the toolpath follows a helical path corresponding to the pitch of the thread.

Corner Rounding



The Corner Rounding toolpath is specifically designed for the application of corner rounding tools to an edge of a part. It is applied to a selected chain, and is similar to the chamfer operation as the Z level of the toolpath is set relative to the selected geometry chain.

Clean Circle

This function creates a pocketing toolpath optimized for circular geometry boundaries.


The method of defining these Stock Toolpaths is very similar to the toolpaths we have already covered. For detailed instructions see the relevant topics in the Mill Stock Toolpaths section of OneCNC Help.

OneCNC Mill Tutorial 6

Toolpath Templates


This tutorial is intended for all levels of OneCNC Mill.

For each toolpath strategy other than Hole Feature Recognition, OneCNC saves the settings you use so you can refer to them later and re-use them easily. Hole Feature Recognition saves its own templates separately as Hole Definitions. Template settings are available in any part you are working on, so you can confidently apply tested settings to new parts.



Each time you start OneCNC, you are given the opportunity to open with a custom user profile, by clicking the arrow beside the user name in the lower left corner of the startup screen. If you do not save a custom name, settings will be applied to the Default User profile.

As well as saving OneCNC customization settings, your user profile also saves your own CAM templates automatically. You can save a template you want to use often as a favorite, giving it a more descriptive name so you can find the template you want to use easily.




As you create toolpaths, the settings you use are listed in the history section of the Templates panel, on the left of the toolpath dialog pages.

When you are defining a toolpath, double-clicking on a template will reload the settings that were used for that toolpath in all the toolpath wizard dialogs.


As an example, we will start by saving a template for a pocket toolpath. In Mill Tutorial 2, we created a HS Pocketing operation. To access the settings for the pocket toolpath, open the file containing the operation.


Right click on the Mill Pocketing operation, and select Edit Operation from the context menu.



Before saving a template as a favorite, you should step through the toolpath wizard, checking the tool and settings used as you go, until you reach the last dialog in the wizard.

When you reach the end of the toolpath wizard, right click in the templates area at the left of the screen, and select Save settings from the context menu.






The Save Template dialog opens.

Type a name for your operation in the entry box at the top of the dialog.

This operation has been named '20 BN Z-25.4 Aluminium'




Once saved, the template appears in the favorites list of the Templates panel.


To guard against accidental editing, you can lock the template by clicking on the padlock icon next to the star.

To re-use a template, all you need to do is start the toolpath, and double-click the template name you want to use.


To see this in action, open your Tutorial Mill 5 file and turn on the Chain 2D layer. Click on the Stock Toolpaths icon and select the HS Pocketing toolpath.



Select the boundary and right click to end the selection process.




Double-click on the template you just saved and all the dialogs of the toolpath wizard will be pre-loaded with the template settings. Step through the dialogs of the wizard without changing any settings, and click Finished.




You will see the saved pocketing toolpath settings applied to the new rectangle.

It is important to understand that a template is simply a method of pre-filling the wizard settings, which can still be changed after the template has been selected.

One time-saving way to build your template set is to use an existing template as a basis for a new one. Right click on your new pocketing operation, and select Duplicate operation from the context menu.




Double click on the duplicate operation, and rename it Mill Pocketing Steel in the NC Processing dialog. Click on the Edit Operation icon to change the settings in the duplicate operation.




When the Select Tool dialog appears, double click on the template to make sure it is loaded. Change the Stock Material to Steel Free Machining.


Click Next and proceed to the last dialog of the toolpath wizard.



Right click in the Templates area, and select Save settings.



Enter the new name, 20 BN Z-25.4 Steel, and lock the new template.



The original template will be unaffected.

You now have two pocketing templates which can be applied quickly and easily.

You can use settings saved for a tool from the history and change the settings on the way through.

For example, if you have a 10mm end mill and as a result of sharpening it is now 9.7mm, you can load a 10mm favorite, then change the size to 9.7. As you step through the toolpath wizard, settings such as stepover will be recalculated automatically.


If you do not save the settings, your templates will not be affected.

OneCNC Mill Tutorial 7

Model Toolpaths - Z Level Rough, Planar Finish

This tutorial is intended for OneCNC: **Mill Advantage**
Mill Professional
Mill Expert

This tutorial is an introduction to solid model machining.





Model toolpaths are usually defined in two stages, roughing to remove the bulk of the material, and then a finishing method to cut the surface itself. For some models a semi-finish operation, which uses a finish strategy with coarser settings than usual, will be useful.

Open the sample file and save a copy.

We will open a sample file with machining already defined, and copy the example operations in a new toolpath group. Open the sample file 'mill advantage z level planar.ONECNC', and use the Save As command on the file menu to save a copy of the file as Tutorial Mill 7 to practice in.

There is an example Toolpath Group already defined in the NC manager.

Right click on the group and select Simulate/Rest from the context menu.



Enter the stock extents as shown in the simulation settings dialog and click OK.

You will see the simulation as shown at the beginning of this tutorial.

We will now replicate the toolpaths in a new group.



If you are using Mill Advantage, only the Traditional roughing mode is available for Z Level Roughing.

Right click on the Example Toolpath group and select New Group from the context menu.


Double click on the new group name in the NC Manager, and rename it to 'Practice Toolpath Group' in the Process dialog.



Z Level Rough toolpath




Click on the Model Toolpaths icon and select the Z Level Rough toolpath.




In the Select Tool dialog, select the 25mm bullnose cutter from the Tool Changer. Enter Tool No. 1, and select Coolant No.1 and Work Offset G54. Select Aluminium Billet Stock.

For Mill Professional or Expert, select the Adjust high feedrate check box and enter a value of 5000. This is the feedrate at which the tool repositions in a High Speed toolpath.

Click Next to continue.



In the Clearances dialog, set the Rapid Z Plane at 5, and the Plunge clearance to 1.




The next step is to select the Machining Style.

If you are using Mill Advantage, you must use Traditional.

If you are using Mill Professional or Expert, choose Highspeed Open.

Click Next to continue.




The settings in the next dialog determine how the tool enters the material.

For the Traditional strategy, select Plunge entry, Climb milling and Spiral inwards.

For the Highspeed strategy, you only need to choose Plunge entry, as the other factors are set by the High Speed toolpath.

Click Next to continue.




Set Auto stepover to 25%, and leave on sides to 0.5


Clear the Leave on bottom check box. Leave Tolerance at the default setting of 0.005.

For Mill Advantage set Depth of Cut to 5.5.

For Mill Professional or Expert set Depth of Cut to 15, select Reduce Steps and enter a setting of 1.



For the Traditional method being used in Mill Advantage, the next dialog will allow you to set Custom levels if desired. For this operation select the Find Flat Areas option, which will create a cut level for the flat at the top of the block.



The Boundary of Toolpath settings define the 3D toolpath zone. As you change settings in this dialog the preview of the toolpath extents will update to show the effect of the changes.

Select the Extents Box boundary type. This defines the zone by simple X, Y, and Z limits. Select None for tool placement, which allows the cutter centerline to travel up to the boundary.

OneCNC can calculate an automatic offset from the model.

Select the Automatic Z check box, and set a value of 1 for Automatic Z offset. For this model, the Automatic Z offset is necessary to allow the toolpath to machine the top face of the model.

Select the Automatic XY check box, and enter 0 for Automatic XY offset.


Click Finished to create the toolpath.

Note:




If the Picked boundary type is selected, you will only have Z options at this stage. The XY area of the toolpath is then defined by picking a geometry boundary.

Simulate the new Z Level Rough toolpath and you will see the material removal progressing down in Z.





If you are using the Traditional toolpath strategy the roughing will appear with larger steps as shown.



With the Step Reduction technology included with OneCNC Professional and Expert you will see a result with smaller steps.

Planar Finish toolpath

Now that we have roughed out the stock, we will use the Planar finish strategy, which runs the toolpath across the model surface at intervals.




Click on the Model toolpaths icon and select the Planar Finish toolpath.

SMT Planar Finishing

Templates : favourites history

Select Tool



Tool No. 2 V1 None

Length Offset 2 V2 None

Diameter Offset 2 V3 None

Spindle Speed 5490 V4 None

Spindle Direction ☐ CCW ☒ CW

Coolant No.1

Work Offset G54

Feedrate 373 Feed Control

Plunge Rate 187

Tool Changer

Holder 20 MM ER COLLET CHUCK

Tool Type Ball 16 MM CARBIDE BALL MILL

Overall Length 60

Flute Length ☒ 26

Diameter 16

Tool Zero Position Tip

Name : 2:Planar Finish


Stock Material Aluminium Billet

Notes...

< Back > Next X Cancel


Select the 16mm carbide ball mill tool from the Tool Library. Enter Tool No. 2, and select Coolant No.1 and Work Offset G54. Select Aluminium Billet Stock.

Click Next to continue.



In the Clearances dialog, set the Rapid Z Plane at 5, and the Plunge clearance to 1.

The Planar Cut Options give you control over how the cut is achieved.




Set Direction to Zigzag, which allows the cutter to travel back and forth across the model. Single direction cut is possible, but this creates longer repositioning moves.

Set Toolpath angle, Zigzag minimum clearance and Leave for finish to 0.

Set surface tolerance, which controls how closely the toolpath follows the theoretical surface, to 0.005.

Select Maximum stepover and enter a value of 0.8.



Select the Extents Box boundary type. Select None for tool placement, which allows the cutter centerline to travel up to the boundary.


Clear the check box for Automatic Z Offset.

For Z Top, enter -7. As the ball cutter radius is 8, this is enough to ensure the cutter passes over the entire shaped surface, without running over the edge to the flat surface.

Set Z Bottom of Job to -80.

Select the Automatic XY check box, and enter 1 for Automatic XY offset.

Click Finished and the toolpath will be created. You will see a red outline traverse the model as the toolpath is being calculated.



Simulate the toolpath group and you will see the Planar finish in action.

To complete this model the holes need to be drilled. Right click on the Drill 2 Holes operation in the example toolpath group, and select Edit Operation to find the settings used to create it. Use the Hole Feature Recognition command to recreate the drilling operation, and the machining will be completed.

On this model we have used Z Level Rough and Planar Finish toolpaths. You have seen the Z Level toolpath descend in steps in Z, and the Planar toolpath increment in the XY plane.


Generally the Z level strategy is more suited to steep surfaces, and planar to lower angles, but of course many models will not be entirely one or the other and you will have to choose a strategy that best fits your purpose. In some cases you may find a combination of strategies will provide the most efficient results.

OneCNC Mill Tutorial 8

Model Toolpaths - Semi Finishing

This tutorial is intended for OneCNC: **Mill Advantage**
Mill Professional
Mill Expert

Semi Finishing is the application of a Finish strategy with coarse settings, to prepare a roughed model for finishing.



This view shows the stages of machining for the sample we will use. The first operation, seen here at the front of the view, is Z Level Roughing which has left steps on the stock. At the back of the view the Planar finish strategy has been applied.

In between these you can see the semi finishing operation, which has reduced the steps from the Z Level toolpath.

Open the sample file and save a copy.


Click on the Open icon, and navigate to the Samples folder which is located in the Drawings folder where you installed OneCNC.

Open the file 'mill professional planar semi finish.ONECNC', and use the Save As command on the File menu to save a copy as 'Tutorial Mill 8.ONECNC'


You will see in the NC Manager an example toolpath group already defined. We will copy this group and recreate the semi-finishing operation.

Right click on the group and select Duplicate Group from the context menu.



Rename the group to Practice Toolpath Group by double clicking on the group name and changing the Description in the Process dialog.



Right click on the Planar Semi Finish operation in the duplicated group and delete it using the Delete Operation command on the context menu.



Planar Semi Finishing



Click on the Model toolpaths icon and select the Planar Finish toolpath.


SMT Planar Finishing

Templates :

favourites

history

Select Tool



Tool No. 2

V1 None

Length Offset ☐

2

V2 None

Diameter Offset 2

V3 None

Spindle Speed 8785

V4 None

Spindle Direction ☐ CCW ☒ CW

Coolant No. 1

Work Offset G54

Feedrate 316

Feed Control

Plunge Rate 158

Tool Changer

Holder ER20 COLLET CHUCK

Tool Type Ball

10 MM CARBIDE BALL MILL

Overall Length 50

Flute Length ☒ 19

Diameter 10

Tool Zero Position Tip

Name : Z:Planar Semi Finish

Stock Material Aluminium Billet

Notes...

< Back

> Next

X Cancel


Select the 10mm carbide ball mill tool from the tool library, and enter Tool No. 2, Coolant No. 1 and Work Offset G54.

Select Aluminium Billet Stock from the Material list.


Click Next to continue.

Introduction to OneCNC Mill ©

Page 223



In the Clearances dialog, set the Rapid Z Plane at 5, and the Plunge clearance to 1.




In the Planar Cut Options dialog, set Direction to Zigzag, and Toolpath angle and Zigzag minimum clearance to 0.

Set Leave for finish at 0.5 so the toolpath is cutting at an offset from the surface.

Set Surface tolerance at 0.005.

The stepover amount directly affects the quality of surface left by the toolpath. For a semi finish operation we are more interested in material removal. Select the Constant stepover option and enter a value of 3.




In the Boundary of Toolpath dialog, select the Part boundary option. Select None for tool placement, which allows the cutter centerline to travel up to the boundary.

Select the check box for Automatic Z Offset, and enter a value of 1. Click Finished and the toolpath will be created.



The new operation is added to the end of the toolpath group. We will move it to the correct position, but to make sure we do not confuse the semi finish and finish operations, we will rename the operation before doing so.

Double click on the operation name and change the Description in the Process dialog to 2:Planar Semi Finish.



With the cursor over the new operation, hold down the left mouse button and move the operation up until a line appears between the Z Level Rough and Planar Finish operations.

Let go of the mouse button and the operation will be inserted where the line appeared.




Simulate the toolpath group and you will see the semi finish operation after the initial roughing is complete.

OneCNC Mill Tutorial 9

Multiple Parts

This tutorial is intended for OneCNC: Mill Professional, Mill Expert

The Multiple Parts tab in the NC Processing dialog has functions which allow you to define toolpaths for a single part, and then specify copies of the toolpaths to cut as many copies of the part as you need.




Repeats can be applied to individual operations or complete toolpath groups.

There are two methods of writing repeats in the NC file.

Standard repeats are written in full in the NC file. This is simple for the operator but can create large files.

For subroutine repeats, OneCNC writes one NC file with each of the original toolpath operations written once as a separate subroutine. The subroutines are then called as required for each position using a work offset.

Standard repeats / one work offset




Can be applied to a toolpath group or a single operation. OneCNC writes the toolpath for each repeat operation, using the same program origin position. Because each operation is written completely for each position, OneCNC can rotate the repeated toolpath if desired.

The standard repeats method will create a larger NC file. If your machine has the capability, you can use a subroutine method.

Subroutine / vices / multiple work offsets

Can only be applied to a toolpath group. The repeats defined with this method are used for vice positions assigned to individual G codes such as G54 , G55, and so on.




Each subroutine will be run at each location, by writing the work offset G code (G54, G55 etc) for each location before each subroutine call. As the offset positions are set on the machine and not in OneCNC, the machine operator must set the offsets correctly, and this method cannot be backplotted or simulated.

On a Heidenhain controller, use the 'one work offset / G52' subroutine method instead, which the Heidenhain Post will convert to a CYCLE DEF 7 Datum Shift.


Subroutine / multiple parts / one work offset / G52

Can only be applied to a toolpath group.




Like the multiple offsets method, OneCNC writes each of the toolpath operations as a separate subroutine in one NC file. Each subroutine will run at each offset location, which will be written to the G52 work offset. This method can be backplotted or simulated.

Defining repeats



To practice defining repeats, open the 'spacer block.ONECNC' sample file, and save a copy as 'Multiple parts tutorial.ONECNC'


In the NC manager, there is an example toolpath group to machine the block. We will use the repeat functions to generate copies of the toolpaths in this group.



The first step when defining repeats is to find the spacing between parts, which must allow for the diameter of the cutter used to cut the part profile, and any leave for finish or lead-in/lead-out values.

Before continuing, we will minimise the lead-in and lead-out settings for the part profiling operation. Double click on the 'Outer Mill Profile' operation, and click on the Edit Operation icon in the NC Processing dialog. Step through the dialogs without making any changes till you reach the Entry/Exit Conditions page.

Change the Leadin Radius to 1, and Leadin Angle to 45. Change the




Entry values :		Exit values :	
Leadin Radius	1	Leadout Radius	1
Leadin Angle	45	Leadout Angle	45
Start Line Length	1	End Line Length	1
Start Line Angle	0	End Line Angle	0

Start Line Length to 1 and set the Start Line Angle at 0. Copy the Entry values to the Exit values input boxes, and click Finished.


The required array distance can now be found by backplotting the profile operation and measuring using the Verify tools. For this part we will round the distance up to 180 in X and 130 in Y.

Create 3 duplicates of the original toolpath group, and name them Standard Repeats, Multiple Offset, and Single Offset.




Standard repeats

Double click on the heading of the Standard Repeats toolpath group, and select the Multiple Parts tab in the NC Processing dialog.




For this exercise, select the standard repeats option, and click on the copy array button to open the array dialog.



We will now make array copies of the part, using the spacing we determined earlier. Enter 2 for number of parts in Y, with a Y distance of 130. Enter 2 for number of parts in X, with an X distance of 180.


Click OK and you will see the original position and the three repeats listed in the Positions pane of the Multiple Parts tab.




Selecting a position will show the instant preview of the toolpath in the drawing window. You can double click on a repeat in the positions list to rename it. For a backplot of an individual repeat, select the repeat and click the Backplot icon.

Click OK to close the NC Processing dialog. You will see 'x3' after the title of the group, indicating the number of repeated positions.

Simulate the toolpath group, using the Extents option for stock definition.



Select the check box for Automatic Offset, and set it and Top of Job to 0.



You will see how the simulation sets the simulation stock to include the repeats.



When a toolpath group is repeated, each operation is carried out at each repeat location before processing continues to the next operation, reducing the number of tool changes.

Here you can see the pocketing has been carried out for each repeat before the hole feature operation begins.

Subroutine repeats using multiple offsets

To use the multiple offsets method, it is only necessary to specify the number of vices or positions required, and assign the offsets to the repeats.


Double click on the Multiple Offsets toolpath group, and select the Multiple Parts tab in the NC Processing dialog.



Select the subroutine / vices / multiple work offsets option.
Enter 4 in the input box which appears for Number of vices.
You will see the repeats appear in the Positions pane of the dialog.




This method is not suitable for use with a Heidenhain controller. Use the 'one work offset / G52' subroutine method instead, which the Heidenhain Post will convert to a CYCLE DEF 7 Datum Shift.



To assign an offset position to a repeat, select the repeat in the Positions window, and then select the offset code in the Work offset box. Here we are assigning G55 to the first repeat after the original position. The offset will appear after the repeat name.

Assign G56 to the next repeat, and G57 to the last repeat.

Click OK to confirm the specified repeats. The x3 symbol will appear in the Toolpath Group title bar, indicating the original position will be repeated 3 times.



As we have only selected the work offsets for each repeat by their relative codes, which must be set on the machine itself, OneCNC has no information about the actual repeat position.

This means when defining repeats in this way it is only possible to backplot or simulate the original position.



If you are not the machine operator, you must provide accurate information for the toolpath size with the NC file so each repeat position can be located on the machine with sufficient spacing.



Backplot the part and measure the toolpath, including any lead-in or lead-out present.

Subroutine repeats using a single offset

Subroutine repeats defined by re-writing the same offset each time are defined in the same way as standard repeats, but can only be copy array or copy move repeats.

Double click on the Single Offsets toolpath group, and select the Multiple Parts tab in the NC Processing dialog.


This time select the subroutine / one work offset / G52 option.



Click on the copy array icon and define the same array as before, for 2 parts in each direction, with a Y distance of 130, and an X distance of 180.



Having a correctly formatted Post for your machine is essential for the subroutine methods. Detailed information about posting formats for various machines is available in the Mill> Multiple Parts section of OneCNC Help.



The repeats appear in the Positions menu as before.

There is no need to enter the Work offset code as this is handled automatically in the Post.

This method can be backplotted and simulated in the same way as for standard repeats, as the array distances have been defined in OneCNC. The difference between the two methods will only become apparent when the NC file is posted.



Output for individual repeats can be turned on and off by clicking the On/Off icon in the Multiple Parts tab.

If you have tested your toolpaths in the original position, you can turn off the output for that position to save time when you run the repeats on the machine.

OneCNC Mill Tutorial 10

Advanced Solid Model Toolpaths

This tutorial covers toolpaths only available in Mill Expert


In this tutorial we will describe the advanced machining strategies provided by Mill Expert.

Roughing strategies

Plunge
Radial
Spiral
Custom

Finish strategies

Radial
Spiral
Custom
Area Machining
Valley Machining
Z Level Complete
Undercut
Constant Offset
Offset
Pencil tracing
Planar steep
Planar shallow




Detailed guides to these toolpaths are provided in the Mill SMT 3D Toolpaths section of OneCNC Help.

By this stage you should be familiar with the common OneCNC toolpath wizard settings, and we will only describe the features of each strategy, and the situations suited to their use.

Plunge Roughing

Plunge roughing is a highly effective material removal strategy which drives the cutter down in the Z axis at increments in X and Y.



When used with a suitable tool, which must be able to end cut and remain centered, plunge roughing virtually eliminates lateral flexing of the cutter.


There are two options to select from for the plunge roughing stepover. Conventional calculates the X and Y stepover based on the tool size. Manual activates input boxes so you can enter the stepover values you want to use.

To see an example of plunge roughing, open the sample file 'mill expert plunge rough machining.ONECNC', and simulate the sample toolpath group.

Radial Roughing

Radial Finishing

Parts with surfaces revolved about an axis parallel to the Z axis are suited to Radial machining, especially when the surface slope is towards or away from the center of revolution.



When you define a Radial toolpath you will be prompted for a center for the radial moves, which must be defined as a point entity.

The tool travels over the model on lines which radiate from a center. Each pass is offset by a degree increment entered in the Radial Options dialog, where you can also specify a start and finish angle.


The radial strategy is not as efficient near the center of the toolpath as the radial offsets become closer and the effective stepover reduces.

To see how radial machining works, open the sample file 'mill expert radial finish.ONECNC', and open the Radial Finish toolpath for editing so you can see the settings used.

Spiral Roughing

Spiral Finishing

The application of spiral toolpaths is similar to radial toolpaths. It is most suited to parts which do not have a steep surface slope towards or away from the center of revolution.



When you define a Spiral toolpath you will be prompted for the center of the spiral toolpath, which must be defined as a point entity.


The tool follows a spiral path around the part. The spiral expands with a constant stepover amount which is defined in the Spiral Options dialog.

To see spiral machining in action, open the sample file 'mill expert spiral machining.ONECNC'. You will see a Spiral Finish operation in the NC Manager.

Custom Roughing

Custom Finishing

Custom Roughing and Finishing toolpaths give you a powerful method of model machining by using geometry drawn in 2D to define the XY travel of a toolpath on a 3D model.



To machine the surface, draw the 2D geometry you want the toolpath to follow on a separate layer so it can be selected easily. The geometry can be drawn manually, or generated by a hatch pattern or backplot of any 2D operation.


When you generate the toolpath you can select the geometry by layer.

The toolpath can have an optional engrave distance so it will cut into an existing model.

This example shows a hatch pattern engraved onto an existing surface.

Area Machining

Area Machining is a unique strategy for machining surfaces which automatically generates a 3D boundary of a set of surfaces.




Area machining requires the selection of one or more surfaces that are adjoining and clear from other objects.

The surfaces are then machined by offsetting the 3D boundary over the surfaces.

Area Machining is not suitable for machining a vertical face on its own, as the 3D offset would cause the tool to spiral around, cutting on the full side of the tool. It is possible however to machine a vertical face when it is selected together with other curved surfaces, as the 3D offset generated will be more suitable.

Valley Machining

Valley Machining is designed for specialized finishing of intricate parts. Larger tools can be used for roughing and finishing parts with internal fillets, then the fillets can be finished with a smaller ball mill by Valley Machining.



The strategy will generate multiple passes to finish any fillets with a radius equal to or smaller than the tool.

When you define a Valley Machining operation, OneCNC automatically identifies any fillets with a radius that can be machined with the selected ball mill, and creates toolpaths to clean up those fillets.


Open the sample file '1_valley machining 3axis.ONECNC' to see an example of Valley Machining in use.

The sample model has 1.9mm radius fillets around the webs, which can be finished using Valley Machining.

Click on the example Valley Machining operation in the NC Manager and you will see it uses a 3mm diameter ball mill tool.

Z Complete Finishing

Z Level Complete finishing is similar to Z level finishing, but when the toolpath finds surface areas which are level or near level, the strategy automatically changes to an offset toolpath to finish those areas.




It is suited to parts which have a combination of steep and flat areas.

Defining a Z Level Complete toolpath is similar to defining a Z Level toolpath.

The Z level increments can be specified as Constant Depths or Maximum stepover. The value entered will also determine the horizontal stepover used on flat areas when the toolpath changes from Z Level to Offset machining.

Undercut Finishing.

Undercuts can be made by the use of a spherical ball mill, or 'lollipop' tool, which has a shank diameter smaller than the ball diameter.



OneCNC prevents the shaft from contacting the part, so the amount of undercut possible is determined by the tool size.

To see an Undercut toolpath in action, open the sample file '3_axis_lollipop.ONECNC', and simulate the toolpath.


This image shows a sectioned view of the simulation. The axis of the hole is 5 degrees from vertical, meaning the right side of the hole cannot be cut with a normal end or ball mill.

The Select Tool dialog for this strategy has a setting for Shaft clearance, which is the clearance used by OneCNC to prevent the shaft from contacting the model.

When defining an undercut toolpath, the Position dialog will appear so you can select a retract position at a safe distance from the overhang. It is recommended that you draw a point entity to use for the retract position.

Constant Offset

By using a boundary similar to the shape of the part, Constant Offset Machining can create a uniform toolpath over the machined area.




Because the boundary controls the flow of the tool path it is possible to create a good machining flow over part shapes which are otherwise difficult to machine.

Vertical faces are not suitable for Constant Offset Machining, these can be done more efficiently with Mill Profile or Z Level finishing. Most mould work does not have true vertical faces anyway, a taper of just 1 degree means it is not a vertical face and is suitable for Constant Offset Machining.

Offset Finishing

Offset machining cuts the part model in passes offset at a regular stepover from a boundary.




This toolpath is useful for unusual shapes or shapes with large or irregular openings.

To define an Offset toolpath you will need an outer boundary, and you can also select inner boundaries to define islands you do not want machined. The boundaries must be closed chains of entities but can be 2D or 3D. One click on any entity in a closed chain will select the entire connected boundary.

When the toolpath is generated, passes are made at offsets from the boundaries across the model surface. The stepover is defined in the Offset Path Options dialog and is the maximum stepover across the model surface.

Pencil Trace Finishing

The Pencil Trace toolpath strategy is designed to identify and pencil finish fillets using a ball mill.



The strategy will generate a single pass to finish any fillets with a radius equal to or smaller than the tool.

When you define a Pencil Trace operation, OneCNC automatically identifies any fillets with a radius that can be machined with the selected ball mill, and creates single pass toolpaths to clean up those fillets.


Open the sample file 'pencil_mm.ONECNC' to see an example of the Pencil Trace operation.

The sample model has 3mm radius fillets around the bases of the cylinders, which can be finished using Pencil Tracing.

Click on the example Pencil Tracing operation in the NC Manager and you will see it uses a 6mm diameter ball mill tool.

Planar Steep Wall Finishing

Planar steep finishing is designed to cut specific areas of the part model based on their angle from the horizontal plane.




This toolpath strategy is optimized for areas with a steep wall angle.

The settings for Planar Steep Wall machining are similar to the Planar Finishing toolpath, with the addition of settings for slope Start Angle and slope Finish Angle. Any part of a surface in the toolpath zone which has a steepness angle within these limits will be machined.

The areas are cut in parallel passes like a planar finishing cut. The angle of the passes from the X axis can be changed to suit the job. There is an additional option to make passes at right angles to the basic angle where that direction would be more suitable for the slope.

Planar Shallow Finishing

Planar shallow finishing is designed to cut specific areas of the part model based on their angle from the horizontal plane.



This toolpath strategy is optimized for areas with a shallow wall angle.

The settings for Planar Shallow machining are similar to the Planar Finishing toolpath, with the addition of settings for slope Start Angle and slope Finish Angle. Any part of a surface in the toolpath zone which has an angle from the XY plane within these limits will be machined.

The areas are cut in parallel passes like a planar finishing cut. The angle of the passes from the X axis can be changed to suit the job. There is an additional option to make passes at right angles to the basic angle where that direction would be more suitable for the slope.

OneCNC Support

For assistance contact the OneCNC office for your location.

If you are emailing a support question, it will help us to help you if you zip and attach the file you are having a problem with, and include the following information:

Client Number

Click on Help > About OneCNC. Your client number is a five digit number with the prefix CN. The number is the same as your dongle number.

Version

Click on Help > About OneCNC to find the exact version you are running, e.g. 51.10

OneCNC product

The type and level of OneCNC such as Mill Expert.

Units

Please let us know if the file is drawn in metric or imperial units.

OneCNC Global Offices

Australia

OneCNC Australia

Phone +61 (0)7 3286 2527
Fax +61 (0)7 3286 4992
Email support@onecnc.com.au
Internet www.onecnc.com.au

Benelux

OneCNC Benelux

Phone +31 (0) 40 22 66 212
Fax +31 (0) 40 22 40 794
Email support@onecnc.nl
Internet www.onecnc.nl

Denmark

OneCNC Denmark

Phone + 45 20 40 02 68
Fax + 45 20 40 02 68
Email support@onecnc.dk
Internet www.onecnc.dk

France

OneCNC France

Phone + 33 (0)4 72 33 38 74
Fax + 33 (0)4 72 91 42 92
Email support@onecnc.fr
Internet www.onecnc.fr

Germany

OneCNC Germany

Phone +49(0)5261 288940
Fax +49(0)5261 2889449
Email support@onecnc.de
Internet www.onecnc.de

India

OneCNC India

Phone +61 7 3286 2527
Email support@onecnc.com.au
Internet www.onecnc.in

Indonesia

OneCNC Indonesia

Phone +62 31 8411187
Email support@onecnc.id
Internet www.onecnc.co.id

Ireland

OneCNC Ireland

Phone +353 7196 33200
Fax +353 7196 33500
Email support@onecnc.co.uk
Internet www.onecnc.co.uk

Italy

OneCNC Italy

Phone +39 393 438 3373
Fax +39 178 271 6215
Email support@onecnc.it
Internet www.onecnc.it

Japan

OneCNC Japan

Phone +81 (0)72 760 3134
Fax +81 (0)72 760 3135
Email onecnc@onecnc.co.jp
Internet www.onecnc.co.jp

Korea

OneCNC Korea

Phone + 82 31 695 7250
Fax + 82 31 695 7253
Email support@onecnc.kr
Internet www.onecnc.kr

Mexico

OneCNC Mexico

Phone +52 (55) 85017429
Email esanchez@onecnc.com.mx
Internet www.onecnc.com.mx

Portugal

OneCNC Iberia

Phone +34 936 473 117
Email josep.soler@1cnc.es
Internet www.onecnc.es

Poland

OneCNC Poland

Phone +48(0)22 388 3460
Fax +48(0)22 388 3461
Email support@onecnc.pl
Internet www.onecnc.pl

South Africa

OneCNC South Africa

Phone +27 31 7014732
Fax +27 31 7014736
Email sredman@iafrica.com
Internet www.onecnc.net

Spain

OneCNC Iberia

Phone +34 936 473 117
Email josep.soler@1cnc.es
Internet www.onecnc.es

Sweden

OneCNC Sweden

Phone +46 (0)35-7777030
Fax +46 (0)35-7777031
Email support@onecnc.se
Internet www.onecnc.se

Taiwan

OneCNC Taiwan

Phone + 886 2 26665010
Fax + 886 2 26660917
Email chou@wvision.asia
Internet www.onecnc.com.tw

United Kingdom

OneCNC UK

Phone +44 (0) 190 237 3054
Fax +44 (0) 190 237 5593
Email support@onecnc.co.uk
Internet www.onecnc.co.uk

USA

OneCNC LLC

Toll Free +1 877 626 1262
Phone +1 813 874 2335
Fax +1 813 874 2919
Email support@onecnc.com
Internet www.onecnc.com

USA California

OneCNC West

Phone +1 909 931 7811
Fax +1 909 985 6967
Email support@onecncwest.com
Internet www.onecncwest.com

Copyright Notice

Copyright Notice

Copyright © 2017 All Rights Reserved

This publication or parts thereof, may not be reproduced in any form, by any method, for any purpose.

Trademarks

The following are registered trademarks of QARM Pty Ltd, in Australia and/or other countries: OneCNC XR7, OneCNC XR6, OneCNC XR5, OneCNC XR4, OneCNC XR3, OneCNC XR2, OneCNC XR, OneCNC XP, OneCNC 2003, OneCNC 2000, OneCNC, AusWire, AusMill, AusCAD, AusCADCAM, NCSentry, NCLink.

Third-Party Trademarks

All other brand names, product names or trademarks belong to their respective holders.

QARM Pty Ltd. MAKES NO WARRANTY, EITHER EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, REGARDING THESE MATERIALS AND MAKES SUCH MATERIALS AVAILABLE SOLELY ON AN "AS-IS" BASIS. IN NO EVENT SHALL QARM Pty Ltd BE LIABLE TO ANYONE FOR SPECIAL, COLLATERAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES IN CONNECTION WITH OR ARISING OUT OF PURCHASE OR USE OF THESE MATERIALS. THE SOLE AND EXCLUSIVE LIABILITY QARM Pty Ltd., REGARDLESS OF THE FORM OF ACTION, SHALL NOT EXCEED THE PURCHASE PRICE OF THE MATERIALS DESCRIBED HEREIN.

QARM Pty Ltd reserves the right to revise and improve its products as it sees fit. This publication describes the state of this product at the time of its publication, and may not reflect the product at all times in the future.



Introduction to OneCNC Mill v62.80